Client / Company Name U Cars Manila - Jun Nannichi Year / Make / Model TOYOTA FORTUNER 2012 G 4X2 Plate / Conduction UOY 995 Price 846 K neg. Transmission Manual Transmission  Mileage(Kms) 72,284 km.  Date Inspection Form Mechanic Name JR VISANDE  Total Passed 133 Total for Replacement 0 Total N/A 32 Total Inspection Points 172  EXTERIOR 38 PASSED 29 REPAIR 5 REPLACEMENT 0 N/A 4 BODY PANELS AND BUMPERS NO Evidence of Flood Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Passed Cleared No Evidence of Hail Damage Repair Repair Repair Repair Repair Repair Repair Passed Ok Uniferent Shade / Color Passed Ok Different Shade / Color Passed Ok Loose or missing trim pleces Evidence of poorly repaired accident damage Small rust spots Passed Ok Evidence of poorly repaired accident damage Passed Ok Loose or missing trim pleces Small rust spots Passed Ok			
Plate / Conduction UOY 995 Price 846 K neg.  Price 846 K neg.  Transmission Manual Transmission  Mileage(Kms) 72,284 km.  Date Inspected May 18, 2018  Mechanic Name JR VISANDE  Total Passed 133  Total for Repair 7  Total for Replacement 0  Total Inspection Points 172  EXTERIOR 38 PASSED 29 REPAIR 5 REPLACEMENT 0 NIA 4  BODY PANELS AND BUMPERS NO Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Sody Panel Inspection Passed Ok Different Shade / Color Passed Ok Different Size panel gaps Loose or missing trim pieces Evidence of poorly repaired accident damage Passed Ok Evidence of poorly repaired accident damage Passed Ok		Client / Company Name	U Cars Manila - Jun Nannichi
Price 846 K neg.  Transmission Manual Transmission  Mileage(Kms) 72,284 km.  Date Inspected May 18, 2018  Mechanic Name JR VISANDE  Total Passed 133  Total for Repair 7  Total for Replacement 0  Total N/A 32  Total Inspection Points 172  EXTERIOR 38  PASSED 29  REPAIR 5  REPLACEMENT 0  N/A 4  BODY PANELS AND BUMPERS  NO Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection  No Evidence of Hail Damage Body Passed Cleared  No Evidence of Hail Damage Roy Passed Cleared  No Evidence of Hail Damage Roy Passed Repair RH quarter panel scratches Bumper/Fascia Inspection Repair Repair RH quarter panel scratches Bumper/Fascia Repair Repair Repair Front and rear bumper scratches and chipped offis Faded Paint Passed Ok  Different Shade / Color Passed Ok  Different Shade / Color Passed Ok  Different Shade / Color Passed Ok  Different Size panel Spassed Ok  Different Size panel Passed Ok  Different Size panel Passed Ok  Different Shade / Color Passed Ok		Year / Make / Model	TOYOTA FORTUNER 2012 G 4X2
Transmission Manual Transmission  Carmudi Inspection Form  Mechanic Name  Total Passed  Total for Repair  Total Inspection Points  EXTERIOR  PASSED  29  REPAIR  5  REPLACEMENT  No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Repair  Passed  Repair  Passed  Repair  Rep		Plate / Conduction	UOY 995
Carmudi Inspection Form  Mileage(Kms)  Date Inspected  May 18, 2018  Mechanic Name  JR VISANDE  Total Passed  Total for Repair  Total for Replacement  Total Inspection Points  Total Inspection Poi		Price	846 K neg.
Inspection Form  Mechanic Name  JR VISANDE  Total Passed  Total for Repair  Total Inspection Points  EXTERIOR  PASSED  29  REPAIR  5  REPLACEMENT  N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  No Evidence of Hail Damage  Body Panel Inspection  Repair  Front and rear bumper scratches Bumper/Fascia Inspection Faded Paint  Different Shade / Color Panel  Different shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorty repaired accident  Passed  Ok  Ok		Transmission	Manual Transmission
FORM  Mechanic Name  JR VISANDE  Total Passed  133  Total for Repair  7  Total for Replacement  0  Total N/A  32  Total Inspection Points  172  EXTERIOR  38  PASSED  REPLACEMENT  NIA  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Hail Damage  No Evidence of H	Carmudi	Mileage(Kms)	72,284 km.
Total Passed 133  Total for Repair 7  Total for Replacement 0  Total N/A 32  Total Inspection Points 172  EXTERIOR 38  PASSED 29  REPAIR 5  REPLACEMENT 0  N/A 4  BODY PANELS AND BUMPERS  NO Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Repair Rhd quarter panel scratches and Inspection Passed Ok  Different Shade / Color Passed Ok  Different Shade / Color Passed Ok  Different size panel gaps  Located No Revidence of poorly repaired accident damage  Passed Ok  Repair Passed Ok  Different size panel gaps  Passed Ok  Different Shade / Color Passed Ok  Passed Ok  Passed Ok  Different size panel gaps  Passed Ok  Different size panel gaps  Passed Ok  Different size panel passed Ok  Passed Ok  Passed Ok	Inspection	Date Inspected	May 18, 2018
Total for Repair 7  Total for Replacement 0  Total N/A 32  Total Inspection Points 172  EXTERIOR 38  PASSED 29  REPAIR 5  REPLACEMENT 0  N/A 4  BODY PANELS AND BUMPERS  No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Repair RH quarter panel scratches and Inspection Repair Rh quarter panel scratches and Inspection Passed Ok  Different Shade / Color Panel Different size panel gaps Loose or missing trim pieces Evidence of poorly repaired accident damage Passed Ok  Evidence of poorly repaired accident damage	Form	Mechanic Name	JR VISANDE
Total for Replacement 0  Total N/A 32  Total Inspection Points 172  EXTERIOR 38  PASSED 29  REPAIR 5  REPLACEMENT 0  N/A 4  BODY PANELS AND BUMPERS  No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Repair RH quarter panel scratches Bumper/Fascia Inspection Repair Rh quarter panel scratches Bumper/Fascia Repair Front and rear bumper scratches and Inspection Passed Ok  Different Shade / Color Passed Ok  Different size panel gaps Loose or missing trim pieces Evidence of poorly repaired accident damage  Total N/A 32  Total Inspection Points 172  Total Inspection Points 172  Passed Cleared  Cleared  Cleared Cleared  RH quarter panel scratches and chipped offs Front and rear bumper scratches and Chipped offs Ok  Different Shade / Color Passed Ok  Different size panel gaps Cok  Loose or missing trim pieces Cok  Evidence of poorly repaired accident damage Ok		Total Passed	133
Total N/A  Total Inspection Points  Total Insp		Total for Repair	7
Total Inspection Points    Total Inspection Points   172		Total for Replacement	0
EXTERIOR 38  PASSED 29  REPAIR 5  REPLACEMENT 0  N/A 4  BODY PANELS AND BUMPERS  No Evidence of Flood Damage Passed Cleared  No Evidence of Fire Damage Passed Cleared  No Evidence of Major Damage Passed Cleared  No Evidence of Hail Damage Passed Cleared  Different Shade / Color Passed Passed Ok  Different Shade / Color Passed Ok  Different size panel gaps  Loose or missing trim pieces Evidence of poortly repaired accident damage  EXTERIOR 38  38  PASSED OR  Passed Ok  Different Shade / Color Passed Ok  Different Size panel Gaps  Dok  Dok  Dok  Dok  Dok  Dok  Dok  Do		Total N/A	32
REPAIR  REPLACEMENT  N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Roy Panel Inspection  Bumper/Fascia Inspection  Faded Paint  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident  damage  29  REPAIR  5  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  RH quarter panel scratches  Front and rear bumper scratches and chipped offs  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  O		Total Inspection Points	172
REPAIR  REPLACEMENT  N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Roy Panel Inspection  Bumper/Fascia Inspection  Faded Paint  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident  damage  29  REPAIR  5  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  RH quarter panel scratches  Front and rear bumper scratches and chipped offs  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  O			
REPLACEMENT  N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Body Panel Inspection  Bumper/Fascia Inspection  Faded Paint  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  5  Cleared  Cleared  Cleared  Cleared  Cleared  Repair  RH quarter panel scratches  Front and rear bumper scratches and chipped offs  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  O	EXTERIOR	38	
REPLACEMENT  N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  No Evidence of Hail Damage  Repair  Body Panel Inspection  Repair  Repair  Front and rear bumper scratches and chipped offs  Faded Paint  Passed  Ok  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage	PASSED	29	
BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Major Damage  No Evidence of Hail Damage  No Evidence of Hail Damage  Body Panel Inspection  Bumper/Fascia Repair Front and rear bumper scratches and chipped offs  Faded Paint Passed Ok  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage	REPAIR	5	
BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  No Evidence of Hail Damage  No Evidence of Hail Damage  Repair Passed  Bumper/Fascia Repair RH quarter panel scratches  Bumper/Fascia Repair Front and rear bumper scratches and Inspection  Faded Paint Passed Ok  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage	REPLACEMENT	0	
No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage Repair Repair Repair Front and rear bumper scratches and chipped offs Faded Paint Different Shade / Color Panel Different size panel gaps Loose or missing trim pieces Evidence of Food Differed Shade / Color Passed Evidence of poorly repaired accident damage  Passed Cleared Cleared Cleared RH quarter panel scratches Front and rear bumper scratches and chipped offs Food Ok	N/A	4	
Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Repair Repair Repair Front and rear bumper scratches and chipped offs Faded Paint Passed Ok Different Shade / Color Panel Different size panel gaps Loose or missing trim pieces Evidence of poorly repaired accident damage  Passed Cleared Cleared  Cleared  Ok Cleared  Ok Passed Ok			
Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage Body Panel Inspection Bumper/Fascia Inspection Faded Paint Passed Passed Ok Different Shade / Color Panel Different size panel gaps Loose or missing trim pieces Evidence of poorly repaired accident passed  Cleared Cleared RH quarter panel scratches Front and rear bumper scratches and chipped offs Ok		Passed	Cleared
Damage  No Evidence of Hail Damage  Body Panel Inspection  Bumper/Fascia Inspection  Faded Paint  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident  A passed  Passed  Cleared  Clea		Passed	Cleared
No Evidence of Hail Damage  Body Panel Inspection  Repair  Repair  Repair  Front and rear bumper scratches and chipped offs  Faded Paint  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  Passed  Cleared  Cleared  Cleared  Cleared  Chapter  Repair  Front and rear bumper scratches and chipped offs  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  O		Passed	Cleared
Body Panel Inspection  Repair  RH quarter panel scratches  Repair  Front and rear bumper scratches and chipped offs  Faded Paint  Passed  Ok  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  RH quarter panel scratches  Repair  Front and rear bumper scratches and chipped offs  Ok  Ok  Ok  Ok  Passed  Ok  Ok  Ok  Ok  Ok  Ok		Passed	Cleared
Inspection Chipped offs  Faded Paint Passed Ok  Different Shade / Color Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  Chipped offs  Ok  Passed Ok  Passed Ok  Passed Ok  Passed Ok  Ok		Repair	RH quarter panel scratches
Faded Paint Passed Ok Different Shade / Color Panel Passed Ok Different size panel gaps Passed Ok Loose or missing trim pieces Evidence of poorly repaired accident damage Passed Ok		Repair	
Panel  Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  Passed  Passed  Ok  Ok  Ok  Ok  Ok	Faded Paint	Passed	Ok
Different size panel gaps  Loose or missing trim pieces  Evidence of poorly repaired accident damage  Passed  Passed  Ok  Ok  Ok  Ok  Ok		Passed	Ok
Loose or missing trim pieces  Evidence of poorly repaired accident damage  Passed Ok  Ok  Ok	Different size panel	Passed	Ok
Evidence of poorly repaired accident Passed Ok damage	Loose or missing trim	Passed	Ok
Small rust spots Passed Ok	Evidence of poorly repaired accident	Passed	Ok
	Small rust spots	Passed	Ok

DOORS, HOOD,		
DECKLID, TAILGATE		
Doors Inspection/Alignment	Repair	Driver door edge chipped off
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	N/A	
Tailgate Inspection/Alignment	Repair	Chipped off, lost emblem
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running Boards	Passed	Ok
GLASS AND OUTSIDE MIRRORS		
Windshield Glass Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Repair	RH folding mirror chipped off
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	44	

REPAIR	0	
REPLACEMENT	0	
N/A	19	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	Passed	Ok
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
•		
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread	Dagged	Ok
Depth/Air Pressure Inspection	Passed	OK
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR		
REPLACEMENT	0	
N/A	4	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	N/A	Manual Transmission
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	Passed	Ok
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok

Relative Cylinder Compression Test/Power Balance Readings (check if	N/A	Untested
necessary)	N/A	Untooted
Timing Belt	Passed	Untested Ok
Engine Mounts Inspect Turbocharger		OK
Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Repair	cleaning only
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Repair	cleaning only
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.80 v
Alternator Output	Passed	13.60 v
Diesel Glow Plug System	Passed	Ok
UNDER CHASSIS	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	
Emissions Control Test	N/A	
TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE		
Automatic Transmission/Transaxle	N/A	Manual Transmission

Manual		
Manual Transmission/Transaxle		
, Differential and	Passed	Ok
Transfer Case		
4x4 Hub Operation	N/A	4x2
Universal Joints, CV	14/71	TAL
Joints and CV Joint	Passed	Ok
Boots	Passeu	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	rasseu	OK
Differential/Drive Axle	Passed	Ok
	rasseu	OK .
TIRES AND WHEELS		
Tires Match and Are	Passed	265/65R17
Correct Size		
Wheels Match and Are	Passed	Ok
Correct Size		
Tire Tread Depth –	Passed	2mm
Front Tires (L/R)		
Tire Tread Depth –	Passed	3mm
Rear Tires (L/R)	Description	No
Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	30 psi
Tires (L/R)		·
Tire Pressure – Rear	Passed	32 psi
Tires (L/R)		
Tire Pressure	N/A	
Monitoring System  No Evidence of Wheel		
Curb Damage	Passed	Ok
Wheel Covers and		
Center Caps	Passed	Ok
Rack-and-Pinion,		
Linkage and Boots	Passed	Ok
Control Arms, Bushings		
and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and		
Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)		
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel	Passed	Ok
Cylinders	1 asseu	OK
Brake Pads and Shoes	Passed	Ok
- Front Brakes (L/R)	1 43364	OK.
Brake Pads and Shoes	Passed	Ok
<ul><li>Rear Brakes (L/R)</li></ul>	1 40004	
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Passed	Ok
and Fittings	rassed	On
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK