Client / Company Name   Jocelyn Bucaneg			
Plate / Conduction   YZ 9074		Client / Company Name	Jocelyn Bucaneg
Transmission		Year / Make / Model	2016 TOYOTA VIOS
Mileage(Kms)   8611 km		Plate / Conduction	YZ 9074
Carmudi Inspection Form         Date Inspected         November 9, 2017           Mechanic Name         Ralfh Gata           Total Passed         132           Total for Repair         2           Total for Replacement         0           Total N/A         38           PASSED         33           REPAIR         0           REPLACEMENT         0           N/A         5           BODY PANELS AND BUMPERS         No Evidence of Flood Damage           No Evidence of Fire Damage         Passed           No Evidence of Major Damage         Passed           No Evidence of Hail Damage         Passed           No Evidence of Hail Damage         Passed           No Evidence of Hail Damage         Cleared		Transmission	Manual Transmission
Inspection Form	0	Mileage(Kms)	8611 km
Total Passed		Date Inspected	November 9, 2017
Total Passed   132		Mechanic Name	Ralfh Gata
Total for Replacement	1 01111	Total Passed	132
Total N/A   38		Total for Repair	2
Total Inspection Points 172  EXTERIOR 38  PASSED 33  REPAIR 0  REPLACEMENT 0  N/A 5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage  No Evidence of Hail Damage  Passed Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared		Total for Replacement	0
EXTERIOR 38  PASSED 33  REPAIR 0  REPLACEMENT 0  N/A 5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage Passed Cleared  No Evidence of Fire Damage Passed Cleared  No Evidence of Major Damage Passed Cleared  No Evidence of Hail Damage Passed Cleared		Total N/A	38
PASSED  REPLACEMENT  0  REPLACEMENT  0  N/A  5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared		Total Inspection Points	172
PASSED  REPLACEMENT  0  REPLACEMENT  0  N/A  5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared			
REPLACEMENT  0  N/A  5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared	EXTERIOR	38	
REPLACEMENT  N/A  5  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared	PASSED	33	
N/A  BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared	REPAIR	0	
BODY PANELS AND BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared	REPLACEMENT	0	
BUMPERS  No Evidence of Flood Damage  No Evidence of Fire Damage  No Evidence of Major Damage  No Evidence of Hail Damage  Passed  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared  Cleared	N/A	5	
No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage Passed Cleared			
Damage  No Evidence of Fire Damage  No Evidence of Major Damage  Passed  Cleared			
No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Passed Cleared Cleared Cleared Cleared		Passed	Cleared
No Evidence of Major Damage Passed Cleared  Cleared  Cleared  Cleared	No Evidence of Fire	Passed	Cleared
No Evidence of Hail Passed Cleared	No Evidence of Major	Passed	Cleared
Body Panel Inspection Passed Ok	No Evidence of Hail	Passed	Cleared
	Body Panel Inspection	Passed	Ok

D (E :		
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	Passed	Ok
Tailgate Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	

Deployable Running Boards	N/A	
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Passed	Ok
Inspection		
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate	Passed	Ok
Glass Inspection Wiper Blade		
Replacement	Passed	Ok
Outside Mirror	5 .	01
Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	43	
REPAIR	0	
REPLACEMENT	0	
N/A	20	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	Ok
Safety Belts	Passed	Ok

AUDIO AND ALARM		
SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	N/A	
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	

Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center	Passed	Ok
Armrest/Console		
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND		
MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok

Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door Release	Passed	Ok
LUGGAGE COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	
Vehicle Jack, Tool Kit, Early Warning Device	Passed	Ok
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	N/A	
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	26	

REPAIR	2	
REPLACEMENT	0	
N/A	7	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	N/A	Manual Transmission
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Electronic
Manual Transaxle/Transmission Hydraulic Clutch Fluid	Passed	Ok
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Not tested
Timing Belt	N/A	
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	

COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	N/A	Not tested
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Repair	Cleaning Only
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Repair	Cleaning Only
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.45 v
Alternator Output	Passed	13.87 v
Diesel Glow Plug System	N/A	Gasoline Engine
UNDER CHASSIS	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	Not tested
Emissions Control Test	N/A	Not tested

TRANSMISSION		
TRANSMISSION, TRANSAXLE,		
DIFFERENTIAL AND		
TRANSFER CASE		
Automatic	N/A	Manual Transmission
Transmission/Transaxle	,, .	
Manual Transmission/Transaxle		
. Differential and	Passed	Ok
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV		
Joints and CV Joint	Passed	Ok
Boots		
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked) Differential/Drive Axle	Desert	Ok
	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	185/60R15
Wheels Match and Are		
Correct Size	Passed	Ok
Tire Tread Depth –	Passed	5mm
Front Tires (L/R)	1 asseu	311111
Tire Tread Depth –	Passed	5mm
Rear Tires (L/R) Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passeu	Normai
Tires (L/R)	Passed	30 psi
Tire Pressure – Rear	Descard	22 mai
Tires (L/R)	Passed	32 psi
Tire Pressure	N/A	
Monitoring System		
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and		<u> </u>
Center Caps	Passed	Complete
Rack-and-Pinion,	Passed	Or
Linkage and Boots	rasseu	Ok
Control Arms, Bushings	Passed	Ok
and Ball Joints		

Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok
Power Steering Pump	N/A	Electronic
BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes  – Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes  - Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok