	Client / Company Name	AutoSelect Car Depot/Ralfh Lawrence Reyes
	Year / Make / Model	2016 HYUNDAI ACCENT
	Plate / Conduction	MP 5788
	Transmission	Automatic Transmission
	Mileage(Kms)	10822 km
Carmudi	Date Inspected	October 23, 2017
Inspection Form	Mechanic Name	Jonh Ralfh Gata
. 0	Total Passed	131
	Total for Repair	0
	Total for Replacement	1
	Total N/A	40
	Total Inspection Points	172
EXTERIOR	38	
PASSED	32	
REPAIR	0	
REPLACEMENT	1	
N/A	5	
BODY PANELS AND		
BUMPERS		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok

D (E :		
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	Passed	Ok
Tailgate Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	

Deployable Running Boards	N/A	
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Replace	Cracked
Inspection	· ·	
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade	Passed	Ok
Replacement	rasseu	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	41	
REPAIR	0	
REPLACEMENT	0	
N/A	22	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	Ok
Safety Belts	Passed	Ok

AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD		
and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	N/A	
Navigation System	N/A	
HEAT/VENT/AC/DEFO		
G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	N/A	
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	

Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center Armrest/Console	N/A	
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND		
MATS Interior Odor-Free	Dagged	Ok
	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	N/A	

Door Locks Passed Ok Child Safety Locks Passed Ok Window Controls Passed Ok Remote Decklid Release Fuel Filler Door Release LUGGAGE COMPARTMENT Ok Passed Ok Ok Ok
Window Controls Passed Ok  Remote Decklid Release Fuel Filler Door Release LUGGAGE Ok
Remote Decklid Release Fuel Filler Door Release LUGGAGE  N/A  Ok  Ok
Release Fuel Filler Door Release LUGGAGE  N/A Ok Ok
Release Ok  LUGGAGE
Luggage Compartment N/A Carpet
Luggage Compartment Trim and Cargo Net
Luggage Compartment/Cargo N/A Area Light
Vehicle Jack, Tool Kit, Early Warning Device Passed Ok
Spare Tire Size/Type and Sidewall Inspection Ok
Spare Tire Tread Depth/Air Pressure Passed Ok Inspection
Tire Inflator Kit N/A
Emergency Trunk-Lid Release N/A
DIAGNOSTICS 1
PASSED 1
REPAIR 0
REPLACEMENT 0
<b>N/A</b> 0
MODULE SYSTEM TEST
Perform Self-Test for all CMDTCs Passed Cleared
UNDERHOOD 35
PASSED 28

REPAIR	0	
REPLACEMENT	0	
N/A	7	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Electronic
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic Transmission
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	

COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	N/A	Untested
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Passed	Ok
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.65 v
Alternator Output	Passed	14.22 v
Diesel Glow Plug System	N/A	Gasoline Engine
UNDER CHASSIS	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	Untested
Emissions Control Test	N/A	Untested

TRANSMISSION,		
TRANSAXLE,		
DIFFERENTIAL AND		
TRANSFER CASE		
Automatic Transmission/Transaxle	Passed	Ok
Manual		
Transmission/Transaxle	N/A	Manual Transmission
, Differential and	IN/A	Mariuai Transmission
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV	Danad	Ol.
Joints and CV Joint Boots	Passed	Ok
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)		
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are	Passed	175/70R14
Correct Size Wheels Match and Are		
Correct Size	Passed	Ok
Tire Tread Depth –	Passed	6mm
Front Tires (L/R)	1 40004	Ollilli
Tire Tread Depth – Rear Tires (L/R)	Passed	6mm
Normal Tire Wear	Passed	Ok
Tire Pressure – Front	Passed	20 noi
Tires (L/R)	Passeu	30 psi
Tire Pressure – Rear Tires (L/R)	Passed	30 psi
Tire Pressure		
Monitoring System	N/A	
No Evidence of Wheel	Passed	Ok
Curb Damage	1 40004	
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion,	_	
Linkage and Boots	Passed	Ok
Control Arms, Bushings	Passed	Ok
and Ball Joints	1 43364	ŬN.

Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok
Power Steering Pump	N/A	Electronic
BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes - Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes  - Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok