	Client / Company Name	
	Year / Make / Model	MITSUBISHI MONTERO SPORT 2013 GLX 4X2
	Plate / Conduction	UNQ 614
	Price	868 K neg.
	Transmission	Automatic transmission
Carmudi	Mileage(Kms)	61,985 km.
Inspection	Date Inspected	May 18, 2018
Form	Mechanic Name	JR VISANDE
	Total Passed	135
	Total for Repair	4
	Total for Replacement	0
	Total N/A	33
	Total Inspection Points	172
EXTERIOR	38	
PASSED	31	
REPAIR		
REPLACEMENT	0	
N/A	5	
BODY PANELS AND BUMPERS		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim		Ole
pieces	Passed	Ok
pieces Evidence of poorly repaired accident damage	Passed	Ok

DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Repair	LH rear passenger door scratch
Hood Inspection/Alignment	Repair	Hood chipped off
Decklid Inspection/Alignment	N/A	
Tailgate Inspection/Alignment	Passed	Ok
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running Boards	N/A	
GLASS AND OUTSIDE MIRRORS		
Windshield Glass Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	44	

REPAIR	0	
REPLACEMENT	0	
N/A	19	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
•		
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread	Dagged	Ok
Depth/Air Pressure Inspection	Passed	OK
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR		
REPLACEMENT	0	
N/A	4	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic transmission
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok

D		
Relative Cylinder		
Compression Test/Power Balance	N/A	Untested
Readings (check if	IN//A	Ontested
necessary)		
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger	N/A	
Air Cooler	IN/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator	Passed	Ok
Cap and Radiator		5
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter		
	Repair	cleaning only
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Repair	cleaning only
ELECTRICAL		
SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.76 v
Alternator Output	Passed	14.22 v
Diesel Glow Plug	Passed	Ok
System		OK.
UNDER CHASSIS	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System	21/2	
Condition	N/A	
Emissions Control Test	N/A	
TRANSMISSION,		
TRANSAXLE,		
DIFFERENTIAL AND TRANSFER CASE		
Automatic	D	21
Transmission/Transaxle	Passed	UK
	Passed	Ok

Manual		
Manual Transmission/Transaxle		
, Differential and	N/A	Automatic transmission
Transfer Case		
4x4 Hub Operation	N/A	4x2
Universal Joints, CV		
Joints and CV Joint	Passed	Ok
Boots	1 45504	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	1 45554	
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		-
Tires Match and Are		
Correct Size	Passed	265/65R17
Wheels Match and Are		
Correct Size	Passed	Ok
Tire Tread Depth –		
Front Tires (L/R)	Passed	3mm
Tire Tread Depth –	_	_
Rear Tires (L/R)	Passed	2mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	30 psi
Tires (L/R)	rasseu	30 μsι
Tire Pressure – Rear	Passed	32 psi
Tires (L/R)	1 43304	υΣ μοι
Tire Pressure	N/A	
Monitoring System		
No Evidence of Wheel	Passed	Ok
Curb Damage	. 2000	J
Wheel Covers and	Passed	Ok
Center Caps		
Rack-and-Pinion,	Passed	Ok
Linkage and Boots		
Control Arms, Bushings	Passed	Ok
and Ball Joints	Desert	Ole
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	rasseu	
(check if necessary)	Passed	Ok Based on Tire Wear
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel		
Cylinders	Passed	Ok
Brake Pads and Shoes	_	_
- Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes	_	
– Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses		
and Fittings	Passed	Ok
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK