	Client / Company Name	OLF Auto Center-Othello Fuentabella
	Year / Make / Model	2011 AUDI A4
	Plate / Conduction	PIN 153
	Price	1.280 M
	Transmission	Automatic Transmission
Carmudi	Mileage(Kms)	67021 km
Inspection	Date Inspected	May 18, 2018
Form	Mechanic Name	Ralfh Gata
	Total Passed	138
	Total for Repair	2
	Total for Replacement	0
	Total N/A	32
	Total Inspection Points	172
EXTERIOR	38	
PASSED	32	
REPAIR	2	
REPLACEMENT N/A	0 4	
BODY PANELS AND	4	
BUMPERS		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Repair	Rear Left Panel (Scratched)
Bumper/Fascia Inspection	Repair	Rear Bumper (Scratched)
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok

DOODS HOOD		
DOORS, HOOD, DECKLID, TAILGATE		
Doors		
Inspection/Alignment	Passed	Ok
Hood	Doored	Ok
Inspection/Alignment	Passed	Ok
Decklid	Passed	Ok
Inspection/Alignment	1 40004	
Tailgate	N/A	
Inspection/Alignment	Desced	Ole
Roof Inspection	Passed	Ok
Hood Release	Passed	Ok
Mechanisms Operate Properly	rasseu	Ok
Hood Hinges Operate		
Properly	Passed	Ok
Hood Prop Rod/Gas	Doggod	Ok
Struts Operate Properly	Passed	Ok
Door Hinges Operate	Passed	Ok
Properly	1 40004	O.K
Trunk/Tailgate	Doggad	Ole
Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND		
ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
	N/A	OK
Roof Rack Inspection	IN/A	
Deployable Running Boards	N/A	
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Passed	Ok
Inspection	rasseu	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate	Passed	Ok
Glass Inspection	1 83360	OK .
Wiper Blade	Passed	Ok
Replacement		
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror		
Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior		0:
Lights	Passed	Ok
Back-End Exterior	Passed	Ok
Lights	rasseu	OK
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	Passed	Ok
		<b>5.</b>
Trailer Lamp Connector Operation	N/A	
Trailer Lamp Connector	N/A 63	
Trailer Lamp Connector Operation		

REPAIR	0	
REPLACEMENT	0	
N/A	17	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	N/A	
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	N/A	
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	Passed	Ok
Rear View Camera System)	N/A	
Active Park Assist	Passed	Ok
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
Glove Box		
Center	Passed	Ok
Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	Passed	Ok
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	Passed	Ok
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread	Passed	Ok
Depth/Air Pressure Inspection	Passeu	OK
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic Transmission
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and	Passed	Ok
Fittings		
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok

Relative Cylinder		
Compression Test/Power Balance	N/A	Untested
Readings (check if	IN/A	Onlested
necessary)		
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger	N/A	
Air Cooler	IV/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator	Passed	Ok
Cap and Radiator Cooling Fans, Clutches		
and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise	Deced	Ok
Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL		
SYSTEM Starter Operation	Dagged	Ok
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.47 v
Alternator Output	Passed	13.58 v
Diesel Glow Plug System	N/A	Gasoline Engine
UNDER CHASSIS	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM	rasseu	OK .
Exhaust System		
Condition	N/A	Untested
Emissions Control Test	N/A	Untested
TRANSMISSION,		
TRANSAXLE,		
DIFFERENTIAL AND TRANSFER CASE		
Automatic	_	2:
Transmission/Transaxle	Passed	Ok

Manual		
Manual Transmission/Transaxle		
, Differential and	N/A	Automatic Transmission
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV	14/71	
Joints and CV Joint	Passed	Ok
Boots	rasseu	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	1 45564	OK .
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS	1 40004	OK .
Tires Match and Are	Passed	205/50R17
Correct Size		
Wheels Match and Are	Passed	Ok
Correct Size Tire Tread Depth –		
	Passed	4mm
Front Tires (L/R) Tire Tread Depth –		
Rear Tires (L/R)	Passed	4mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front		
Tires (L/R)	Passed	30 psi
Tire Pressure – Rear	Desert	20:
Tires (L/R)	Passed	32 psi
Tire Pressure	N/A	
Monitoring System	IN/A	
No Evidence of Wheel	Passed	Ok
Curb Damage	rasseu	OK
Wheel Covers and	Passed	Ok
Center Caps	rasseu	OK
Rack-and-Pinion,	Passed	Ok
Linkage and Boots	1 40004	O.K
Control Arms, Bushings	Passed	Ok
and Ball Joints		O.N.
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and	Passed	Ok
Bushings		
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)	1 43364	
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel	Possed	Ok
Cylinders	Passed	Ok
Brake Pads and Shoes	Passed	Ok
- Front Brakes (L/R)	1-035CU	OK .
Brake Pads and Shoes	Passed	Ok
- Rear Brakes (L/R)	1- a335U	On
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Passed	Ok
and Fittings	1- asseu	OK .
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK