	Client / Company Name	Autobase Car Exchange/Noy Andres
	Year / Make / Model	2009/Honda/City
Carmudi	Plate / Conduction	NTO 330
Inspection	Transmission	Automatic
Form	Mileage(Kms)	68578 km
	Date Inspected	03/09/2017
	Mechanic Name / Signature	
EXTERIOR	39	
PASSED	33	
BODY PANELS AND		
BUMPERS No Evidence of Flood		
Damage	Passed	Clear
No Evidence of Fire Damage	Passed	Clear
No Evidence of Major Damage	Passed	Clear
No Evidence of Hail Damage	Passed	Clear
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	Passed	Ok
Tailgate Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
Power Liftgate Operation GRILLE, TRIM AND	N/A	
ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection  Deployable Running	N/A	
Boards	N/A	

GLASS AND		
OUTSIDE MIRRORS Windshield Glass	December	Ole
Inspection	Passed	Ok
Side Glass Inspection Rear Window/Tailgate	Passed	Ok
Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	(Scratched)Headlight Case
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	N/A	
Hazard Lights	Passed	Ok
Auto On/Off Lighting	Passed	Ok
Trailer Lamp Connector Operation	N/A	
INTERIOR	61	
PASSED	40	
CONVENIENCE		
Owner's Guide		
Keys and Remote	Passed	Ok
Controls Full Fuel Level	1 43364	OK .
AIRBAG AND		
SAFETY BELTS		Marile December Althou
Airbags	Passed	With Passenger Airbag
Safety Belts  AUDIO AND ALARM	Passed	Ok
SYSTEMS Radio, Cassette, CD		
and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	N/A	
Navigation System	N/A	
HEAT/VENT/AC/DEF OG/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes		
Instrument Panel and	Repair	ABS Indicator Appear
Warning Lights Windshield Wipers	Passed	Ok
Rear Window Wiper	N/A	
Washers	Passed	Ok
Interior Courtesy,	Repair	Dome Light Passenger Side Broker
Dome and Map Lights Outside Rearview	Passed	Ok
Mirrors	เ ของสน	UK UK

N/A	
Passed	Ok
Passed	Ok
N/A	
Passed	Ok
	Ok
	Ok
	Ok
N/A	
Passed	Ok
N/A	
Passed	Ok
Passed	Ok
	Ok
	Tiny Scratched
Passed	Ok
Passed	Ok
Passed	Ok
Passed	Ok
N/A	
N/A	
N/A	
N/A	
N/A	
Dooosa	Ok
	OK .
N/A	
Passed	Ok
Passed	Ok
Passed	Ok
N/A	
Passed	Ok
D !	Ol.
	Ok
Passed	Ok
Passed	Ok
Passed	Ok
N/A	
N/A	
	Passed N/A Passed Passed Passed Passed Passed Passed N/A Passed N/A Passed N/A N/A N/A N/A Passed Passed Passed Passed N/A N/A N/A Passed

Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release DIAGNOSTICS	1	
PASSED	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	N/A	Untested
UNDERHOOD	35	
PASSED	28	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Chassis Lube		
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmissio n Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Electronic
Manual Transaxle/Transmissio n Hydraulic Clutch Fluid	N/A	
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok

Engine Air Filter  ELECTRICAL	Passed	Ok
SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.32 v
Alternator Output	Passed	13.87 v
Diesel Glow Plug System	N/A	
UNDER CHASSIS	35	
PASSED	28	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		Ok
Exhaust System	N/A	
Condition		
Emissions Control Test TRANSMISSION,	N/A	
TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE		
Automatic Transmission/Transaxl e	Passed	Ok
Manual Transmission/Transaxl e, Differential and Transfer Case	N/A	
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Drive Axle
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	Ok
Wheels Match and Are	Passed	Ok
Correct Size Tire Tread Depth –	Passed	Ok
Front Tires (L/R) Tire Tread Depth –	Passed	Ok
Rear Tires (L/R)		
Normal Tire Wear  Tire Pressure – Front	Passed	Ok
Tires (L/R) Tire Pressure – Rear	Passed	Ok
Tires (L/R)	Passed	Ok
Tire Pressure Monitoring System	N/A	
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Replace	Lacking 1 pc. Center Cap
Rack-and-Pinion,	Passed	Ok
Linkage and Boots Control Arms, Bushings and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and	Passed	Ok
Bushings Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok
(check if necessary)		
Power Steering Pump	N/A	Electronic

BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes - Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes - Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok