	Client / Company Name	Autobase Car Exchange/Noy Andres
	Year / Make / Model	2008/Toyota/Corolla Altis
Carmudi	Plate / Conduction	ZMW 295
Inspection	Transmission	Automatic
Form	Mileage(Kms)	64306 km
	Date Inspected	03/09/2017
	Mechanic Name / Signature	
EXTERIOR	37	
PASSED	33	
BODY PANELS AND		
BUMPERS		
No Evidence of Flood Damage	Passed	Clear
No Evidence of Fire Damage	Passed	Clear
No Evidence of Major Damage	Passed	Clear
No Evidence of Hail Damage	Passed	Clear
Body Panel Inspection	Passed	Small Dent/Scratches
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	Passed	Ok
Tailgate Inspection/Alignment		
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
Power Liftgate Operation		
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	

Outside Rearview	Passed	Ok
Mirrors Auto-Dimming	N/A	
Rear View Camera	N/A	
System) Active Park Assist	Passed	Ok
Rear Entertainment	N/A	On On
System Power Outlets	Passed	Ok
		Ok
Lighter	Passed	
Ashtrays	Passed	Ok
Glove Box Center	Passed	Ok
Armrest/Console Sun Visors, Vanity	Passed	Ok
Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head	Passed	Ok
Restraint Adjustment Folding Seats	Passed	Ok
Heated Seats	N/A	<u> </u>
Cooled Seats	N/A	
Integrated Child Safety	N/A	
Seats SUNROOF/MOONRO	IV/A	
OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	N/A	
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid	N/A	
Release Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT Luggage Compartment	Deersid	Ol.
Carpet Luggage Compartment	Passed	Ok
Trim and Cargo Net Luggage	Passed	Ok
Compartment/Cargo Area Light	Passed	Ok
Vehicle Jack and Tool Kit	Passed	Without Earlt Warning Device
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok

Spare Tire Tread		
Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	N/A	
DIAGNOSTICS	1	
PASSED		
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	N/A	Untested
UNDERHOOD	34	
PASSED	28	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Chassis Lube		
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmissio	Danca -	Ok
n Fluid	Passed	OK
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Ok
Manual Transaxle/Transmissio n Hydraulic Clutch Fluid		
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner	Passed	Ok
Housing Water, Sludge or	Passed	Ok
Engine Coolant in Oil		
Oil Pressure Relative Cylinder	Passed	Ok
Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and	Passed	Ok
Radiator Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise	Passed	Ok
Normal	. 40004	

Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	Ok
Alternator Output	Passed	Ok
Diesel Glow Plug	N/A	Petrol Engine
System UNDER CHASSIS	35	
PASSED	29	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM	i asseu	OK.
Exhaust System	21/2	
Condition	N/A	
Emissions Control Test TRANSMISSION,	N/A	
TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE		
Automatic Transmission/Transaxl e	Passed	Ok
Manual Transmission/Transaxl e, Differential and Transfer Case	N/A	
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Drive Axle
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	Ok
Wheels Match and Are Correct Size	Passed	Ok
Tire Tread Depth –	Passed	Ok/5mm
Front Tires (L/R) Tire Tread Depth –	Passed	Ok/5mm
Rear Tires (L/R) Normal Tire Wear	Passed	Normal
Tire Pressure – Front		
Tires (L/R) Tire Pressure – Rear	Passed	30 psi
Tires (L/R)	Passed	30 psi
Tire Pressure Monitoring System No Evidence of Wheel	N/A	2:
Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion, Linkage and Boots	Passed	Ok
Control Arms, Bushings and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok

Wheel Alignment (check if necessary)	Passed	Ok
Power Steering Pump	N/A	Electronic
BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes - Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes - Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok