Client / Company Name Jay San Juan/Sta. Lucia Car Fair			
Plate / Conduction		Client / Company Name	Jay San Juan/Sta. Lucia Car Fair
Transmission		Year / Make / Model	2016 Hyundai Tucson CRDi
Mileage(Kms) 19455 km		Plate / Conduction	MQ 2665
Carmudi Inspection Form Date Inspected December 1, 2017 Mechanic Name Jonh Ralfh Gata Total Passed 135 Total for Repair 4 Total for Replacement 0 Total N/A 33 Total Inspection Points 172 EXTERIOR 38 PASSED 32 REPAIR 3 REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage Passed No Evidence of Major Damage Passed No Evidence of Hail Damage Passed No Evidence of Hail Damage Passed Cleared Cleared		Transmission	Automatic Transmission
Date Inspected December 1, 2017	0	Mileage(Kms)	19455 km
Total Passed		Date Inspected	December 1, 2017
Total Passed 135		Mechanic Name	Jonh Ralfh Gata
Total for Replacement	1 01111	Total Passed	135
Total N/A Total Inspection Points 172 EXTERIOR 38 PASSED 32 REPAIR 3 REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared		Total for Repair	4
Total Inspection Points 172 EXTERIOR 38 PASSED 32 REPAIR 3 REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared		Total for Replacement	0
EXTERIOR 38 PASSED 32 REPAIR 3 REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Major Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared		Total N/A	33
PASSED REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared		Total Inspection Points	172
PASSED REPAIR 3 REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Replace			
REPLACEMENT 0 N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared	EXTERIOR	38	
REPLACEMENT N/A 3 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared	PASSED	32	
N/A BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared	REPAIR	3	
BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared	REPLACEMENT	0	
BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared	N/A	3	
No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage Passed Cleared			
Damage No Evidence of Fire Damage No Evidence of Major Damage Passed Cleared			
No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared		Passed	Cleared
No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared	No Evidence of Fire	Passed	Cleared
No Evidence of Hail Damage Passed Cleared	No Evidence of Major	Passed	Cleared
	No Evidence of Hail	Passed	Cleared
		Repair	Front passenger side door (Dent)

Bumper/Fascia	Repair	Rear Bumper (Chipped-off)
Inspection	Керап	Real Bullipel (Chipped-Oil)
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Repair	Dent/Chipped-off
Decklid Inspection/Alignment	N/A	
Tailgate Inspection/Alignment	Passed	Ok
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	Passed	Ok

Deale all Deale		
Deployable Running Boards	Passed	Ok
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Passed	Ok
Inspection	1 40004	
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate	Passed	Ok
Glass Inspection		
Wiper Blade	Passed	Ok
Replacement Outside Mirror		
Inspection	Passed	Ok
Outside Folding Mirror		
Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior	Passed	Ok
Lights	1 43364	OK .
Back-End Exterior	Passed	Ok
Lights		
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector	N/A	
Operation		
INTERIOR	63	
PASSED	44	
REPAIR		
REPLACEMENT	0	
N/A	18	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote	Passed	Ok
Controls	rasseu	OK .
AIRBAG AND SAFETY BELTS		
Airbags	Passed	Ok
Safety Belts	Passed	Ok

AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD		
and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	Passed	Ok
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Repair	Service warning indicator appeared
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	

Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND		
MATS Interior Odor-Free	Passed	Ok
	Passed	Ok
Carpet Floor Mats	Passed	Ok
Door Trim and Door	Passeu	
Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	N/A	

Door Locks Passed Ok Child Safety Locks Passed Ok Window Controls Passed Ok Remote Decklid Release Fuel Filler Door Release LUGGAGE	Start	N/A	
Window Controls Passed Ok Remote Decklid Release Fuel Filler Door Release Passed Ok Ok		Passed	Ok
Remote Decklid Release Fuel Filler Door Release Ok	ocks	Passed	Ok
Release Fuel Filler Door Release Ok	ols	Passed	Ok
Release Passed Ok	id	N/A	
LUGGAGE)r	Passed	Ok
COMPARTMENT			
Luggage Compartment N/A Carpet		N/A	
Luggage Compartment Trim and Cargo Net		N/A	
Luggage Compartment/Cargo N/A Area Light		N/A	
Vehicle Jack, Tool Kit, Early Warning Device Passed Ok	Device	Passed	Ok
Spare Tire Size/Type and Sidewall Inspection Ok		Passed	Ok
Spare Tire Tread Depth/Air Pressure Passed Ok Inspection		Passed	Ok
Tire Inflator Kit N/A	t	N/A	
Emergency Trunk-Lid Release N/A	unk-Lid	N/A	
DIAGNOSTICS 1	S	1	
PASSED 1		1	
REPAIR 0		0	
REPLACEMENT 0	NT	0	
N/A 0		0	
MODULE SYSTEM TEST			
Perform Self-Test for all CMDTCs Passed Cleared	est for all	Passed	Cleared
UNDERHOOD 35		35	
PASSED 29		29	

REPAIR	0	
REPLACEMENT	0	
N/A	6	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	

COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	N/A	Untested
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Passed	Ok
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.68 v
Alternator Output	Passed	14.52 v
Diesel Glow Plug System	Passed	Ok
UNDER CHASSIS	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	Untested
Emissions Control Test	N/A	Untested

TDANGAROOLON		
TRANSMISSION, TRANSAXLE,		
DIFFERENTIAL AND		
TRANSFER CASE		
Automatic Transmission/Transaxle	Passed	Ok
Manual		
Transmission/Transaxle , Differential and Transfer Case	N/A	
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	225/60R17
Wheels Match and Are Correct Size	Passed	Correct wheel size
Tire Tread Depth – Front Tires (L/R)	Passed	6mm
Tire Tread Depth – Rear Tires (L/R)	Passed	6mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front Tires (L/R)	Passed	30psi
Tire Pressure – Rear Tires (L/R)	Passed	30psi
Tire Pressure Monitoring System	N/A	
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion, Linkage and Boots	Passed	Ok
Control Arms, Bushings and Ball Joints	Passed	Ok

Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok
Power Steering Pump	N/A	
BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes – Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes – Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok