

| | | |
|--|-------------------------|---------------------------|
| Carmudi Inspection Form | Client / Company Name | BJA Car Hub - Bernie Abad |
| | Year / Make / Model | 2014 HYUNDAI SANTAFE |
| | Plate / Conduction | AAF 4989 |
| | Price | 888 K Negotiable |
| | Transmission | Manual Transmission |
| | Mileage(Kms) | 39112 km |
| | Date Inspected | April 6, 2018 |
| | Mechanic Name | Ralfh Gata |
| | Total Passed | 144 |
| | Total for Repair | 0 |
| | Total for Replacement | 0 |
| | Total N/A | 28 |
| | Total Inspection Points | 172 |
| | | |
| EXTERIOR | 38 | |
| PASSED | 33 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 5 | |
| BODY PANELS AND BUMPERS | | |
| No Evidence of Flood Damage | Passed | Cleared |
| No Evidence of Fire Damage | Passed | Cleared |
| No Evidence of Major Damage | Passed | Cleared |
| No Evidence of Hail Damage | Passed | Cleared |

| | | |
|---|--------|----|
| Body Panel Inspection | Passed | Ok |
| Bumper/Fascia Inspection | Passed | Ok |
| Faded Paint | Passed | Ok |
| Different Shade / Color Panel | Passed | Ok |
| Different size panel gaps | Passed | Ok |
| Loose or missing trim pieces | Passed | Ok |
| Evidence of poorly repaired accident damage | Passed | Ok |
| Small rust spots | Passed | Ok |
| DOORS, HOOD, DECKLID, TAILGATE | | |
| Doors Inspection/Alignment | Passed | Ok |
| Hood Inspection/Alignment | Passed | Ok |
| Decklid Inspection/Alignment | N/A | |
| Tailgate Inspection/Alignment | Passed | Ok |
| Roof Inspection | Passed | Ok |
| Hood Release Mechanisms Operate Properly | Passed | Ok |
| Hood Hinges Operate Properly | Passed | Ok |
| Hood Prop Rod/Gas Struts Operate Properly | Passed | Ok |
| Door Hinges Operate Properly | Passed | Ok |
| Trunk/Tailgate Hinges/Gas Struts Operate Properly | Passed | Ok |
| GRILLE, TRIM AND ROOF RACK | | |
| Grille Inspection | Passed | Ok |
| Trim Inspection | Passed | Ok |

| | | |
|---------------------------------------|--------|-----------------------|
| Roof Rack Inspection | N/A | |
| Deployable Running Boards | N/A | |
| GLASS AND OUTSIDE MIRRORS | | |
| Windshield Glass Inspection | Passed | Ok |
| Side Glass Inspection | Passed | Ok |
| Rear Window/Tailgate Glass Inspection | Passed | Ok |
| Wiper Blade Replacement | Passed | Ok |
| Outside Mirror Inspection | Passed | Ok |
| Outside Folding Mirror Inspection | Passed | Ok |
| EXTERIOR LIGHTS | | |
| Front-End Exterior Lights | Passed | Ok |
| Back-End Exterior Lights | Passed | Ok |
| Side Exterior Lights | Passed | Ok |
| Hazard Lights | Passed | Ok |
| Auto On/Off Lighting | N/A | |
| Trailer Lamp Connector Operation | N/A | |
| INTERIOR | 63 | |
| PASSED | 51 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 12 | |
| CONVENIENCE | | |
| Owner's Guide | Passed | Ok |
| Keys and Remote Controls | Passed | Ok |
| AIRBAG AND SAFETY BELTS | | |
| Airbags | Passed | With Passenger Airbag |

| | | |
|--|--------|----|
| Safety Belts | Passed | Ok |
| AUDIO AND ALARM SYSTEMS | | |
| Radio, Cassette, CD and Speakers | Passed | Ok |
| Antenna | Passed | Ok |
| Alarm/Theft-Deterrent System | Passed | Ok |
| Navigation System | Passed | Ok |
| HEAT/VENT/AC/DEFOG/DEFROST | | |
| Air Conditioning System | Passed | Ok |
| Heating System | Passed | Ok |
| Defog/Defrost | Passed | Ok |
| INTERIOR AMENITIES | | |
| Clock | Passed | Ok |
| Tilt/Telescopic Steering Wheel | Passed | Ok |
| Steering Column Lock | Passed | Ok |
| Steering Wheel Controls | Passed | Ok |
| Horn | Passed | Ok |
| Warning Chimes | Passed | Ok |
| Instrument Panel and Warning Lights | Passed | Ok |
| Windshield Wipers | Passed | Ok |
| Rear Window Wiper | Passed | Ok |
| Washers | Passed | Ok |
| Interior Courtesy, Dome and Map Lights | Passed | Ok |
| Outside Rearview Mirrors | Passed | Ok |
| Auto-Dimming Rearview Mirror | Passed | Ok |
| Rear View Camera System) | Passed | Ok |
| Active Park Assist | Passed | Ok |

| | | |
|---|--------|----|
| Rear Entertainment System | N/A | |
| Power Outlets | Passed | Ok |
| Lighter | Passed | Ok |
| Ashtrays | Passed | Ok |
| Glove Box | Passed | Ok |
| Center Armrest/Console | Passed | Ok |
| Sun Visors, Vanity Mirror and Light | Passed | Ok |
| Adjustable Pedals (if equipped) | N/A | |
| CARPET, TRIM AND MATS | | |
| Interior Odor-Free | Passed | Ok |
| Carpet | Passed | Ok |
| Floor Mats | Passed | Ok |
| Door Trim and Door Panels | Passed | Ok |
| Headliner | Passed | Ok |
| SEATS | | |
| Seat Upholstery | Passed | Ok |
| Seat and Head Restraint Adjustment | Passed | Ok |
| Folding Seats | Passed | Ok |
| Heated Seats | N/A | |
| Cooled Seats | N/A | |
| Integrated Child Safety Seats | N/A | |
| SUNROOF/MOONROOF/CONVERTIBLE TOP | | |
| Sunroof/Moonroof | N/A | |
| Convertible Top | N/A | |
| WINDOWS AND DOOR LOCKS | | |
| Door Handles and Release Mechanisms | Passed | Ok |

| | | |
|--|--------|---------|
| Remote Entry System | Passed | Ok |
| Push-Button Start System | N/A | |
| Door Locks | Passed | Ok |
| Child Safety Locks | Passed | Ok |
| Window Controls | Passed | Ok |
| Remote Decklid Release | Passed | Ok |
| Fuel Filler Door Release | Passed | Ok |
| LUGGAGE COMPARTMENT | | |
| Luggage Compartment Carpet | N/A | |
| Luggage Compartment Trim and Cargo Net | N/A | |
| Luggage Compartment/Cargo Area Light | N/A | |
| Vehicle Jack, Tool Kit, Early Warning Device | Passed | Ok |
| Spare Tire Size/Type and Sidewall Inspection | Passed | Ok |
| Spare Tire Tread Depth/Air Pressure Inspection | Passed | Ok |
| Tire Inflator Kit | N/A | |
| Emergency Trunk-Lid Release | Passed | Ok |
| DIAGNOSTICS | 1 | |
| PASSED | 1 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 0 | |
| MODULE SYSTEM TEST | | |
| Perform Self-Test for all CMDTCs | Passed | Cleared |
| UNDERHOOD | 35 | |

| | | |
|--|--------|---------------------------|
| PASSED | 30 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 5 | |
| FLUIDS | | |
| Engine Oil/Filter Change | Passed | Ok |
| Coolant | Passed | Ok |
| Brake Fluid | Passed | Ok |
| Automatic Transaxle/Transmission Fluid | N/A | Manual Transmission |
| Transfer Case Fluid | Passed | Ok |
| Drive Axle Fluid | Passed | Ok |
| Power Steering Fluid | N/A | Electronic power steering |
| Manual Transaxle/Transmission Hydraulic Clutch Fluid | Passed | Ok |
| Washer Fluid | Passed | Ok |
| ENGINE | | |
| Fluid Leaks | Passed | Ok |
| Hoses, Lines and Fittings | Passed | Ok |
| Belts | Passed | Ok |
| Wiring | Passed | Ok |
| Oil in Air Cleaner Housing | Passed | Ok |
| Water, Sludge or Engine Coolant in Oil | Passed | Ok |
| Oil Pressure | Passed | Ok |
| Relative Cylinder Compression Test/Power Balance Readings (check if necessary) | N/A | Untested |
| Timing Belt | N/A | Untested |
| Engine Mounts | Passed | Ok |

| | | |
|--|--------|----------|
| Inspect Turbocharger Air Cooler | N/A | |
| COOLING SYSTEM | | |
| Radiator | Passed | Ok |
| Pressure-Test Radiator Cap and Radiator | Passed | Ok |
| Cooling Fans, Clutches and Motors | Passed | Ok |
| Water Pump | Passed | Ok |
| Coolant Recovery Tank | Passed | Ok |
| Cabin Air Filter | Passed | Ok |
| FUEL SYSTEM | | |
| Fuel Pump Noise Normal | Passed | Ok |
| Fuel Pump Pressure | Passed | Ok |
| Fuel Filter | Passed | Ok |
| Engine Air Filter | Passed | Ok |
| ELECTRICAL SYSTEM | | |
| Starter Operation | Passed | Ok |
| Ignition System | Passed | Ok |
| Battery | Passed | 13.27 v |
| Alternator Output | Passed | 13.89 v |
| Diesel Glow Plug System | Passed | Ok |
| UNDER CHASSIS | 35 | |
| PASSED | 29 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 6 | |
| FRAME | | |
| Frame Damage | Passed | Ok |
| Fuel Supply System | Passed | Ok |
| EXHAUST SYSTEM | | |
| Exhaust System Condition | N/A | Untested |

| | | |
|--|--------|---------------------|
| Emissions Control Test | N/A | Untested |
| TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE | | |
| Automatic Transmission/Transaxle | N/A | Manual Transmission |
| Manual Transmission/Transaxle , Differential and Transfer Case | Passed | Ok |
| 4x4 Hub Operation | N/A | |
| Universal Joints, CV Joints and CV Joint Boots | Passed | Ok |
| Transmission Mounts (not cracked, broken or oil-soaked) | Passed | Ok |
| Differential/Drive Axle | Passed | Ok |
| TIRES AND WHEELS | | |
| Tires Match and Are Correct Size | Passed | 235/65R17 |
| Wheels Match and Are Correct Size | Passed | Ok |
| Tire Tread Depth – Front Tires (L/R) | Passed | 6mm |
| Tire Tread Depth – Rear Tires (L/R) | Passed | 6mm |
| Normal Tire Wear | Passed | Normal |
| Tire Pressure – Front Tires (L/R) | Passed | 30 psi |
| Tire Pressure – Rear Tires (L/R) | Passed | 32 psi |
| Tire Pressure Monitoring System | N/A | |
| No Evidence of Wheel Curb Damage | Passed | Ok |
| Wheel Covers and Center Caps | Passed | Ok |
| Rack-and-Pinion, Linkage and Boots | Passed | Ok |

| | | |
|---|--------|-----------------------|
| Control Arms, Bushings and Ball Joints | Passed | Ok |
| Tie Rods and Idler Arm | Passed | Ok |
| Sway Bars, Links and Bushings | Passed | Ok |
| Springs | Passed | Ok |
| Struts and Shocks | Passed | Ok |
| Wheel Alignment (check if necessary) | Passed | Ok Based on Tire Wear |
| Power Steering Pump | N/A | Electronic Steering |
| BRAKES | | |
| Calipers and Wheel Cylinders | Passed | Ok |
| Brake Pads and Shoes – Front Brakes (L/R) | Passed | Ok |
| Brake Pads and Shoes – Rear Brakes (L/R) | Passed | Ok |
| Rotors and Drums | Passed | Ok |
| Brake Lines, Hoses and Fittings | Passed | Ok |
| Parking Brake | Passed | Ok |
| Master Cylinder and Booster | Passed | Ok |