	Client / Company Name	Chin Ugarte
	Year / Make / Model	2009 TOYOTA AVANZA G
	Plate / Conduction	KDY 696
	Price	418 K Negotiable
	Transmission	Automatic Transmission
Carmudi	Mileage(Kms)	91954 km
Inspection	Date Inspected	May 9, 2018
Form	Mechanic Name	Ralfh Gata
	Total Passed	133
	Total for Repair	2
	Total for Replacement	0
	Total N/A	37
	Total Inspection Points	172
EXTERIOR	38	
PASSED	33	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
BODY PANELS AND BUMPERS		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
		OI:
Small rust spots	Passed	Ok

DOODS HOOD		
DOORS, HOOD, DECKLID, TAILGATE		
Doors TAILOATE		
Inspection/Alignment	Passed	Ok
Hood	Doored	Ok
Inspection/Alignment	Passed	Ok
Decklid	Passed	Ok
Inspection/Alignment	1 40004	
Tailgate	N/A	
Inspection/Alignment	Desced	Ole
Roof Inspection	Passed	Ok
Hood Release	Passed	Ok
Mechanisms Operate Properly	rasseu	Ok
Hood Hinges Operate		
Properly	Passed	Ok
Hood Prop Rod/Gas	Doggod	Ok
Struts Operate Properly	Passed	Ok
Door Hinges Operate	Passed	Ok
Properly		
Trunk/Tailgate Hinges/Gas Struts	Passed	Ok
Operate Properly	rasseu	OK
GRILLE, TRIM AND		
ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running		
Boards	N/A	
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Passed	Ok
Inspection	1 40004	OK .
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate	Passed	Ok
Glass Inspection	1 40004	
Wiper Blade	Passed	Ok
Replacement Outside Mirror		
Inspection	Passed	Ok
Outside Folding Mirror	5 .	01
Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior	Passed	Ok
Lights	Passed	Ok
Back-End Exterior	Passed	Ok
Lights		
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector	N/A	
Operation	IV/A	
INTERIOR	63	
PASSED	41	

REPAIR	1	
REPLACEMENT	0	
N/A	21	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	N/A	
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
-		•
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Repair	Driver Side Floor Mat(Torn)
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread	Passed	Ok
Depth/Air Pressure Inspection	Passeu	OK
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic Transmission
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and	Passed	Ok
Fittings		
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok

Relative Cylinder		
Compression Test/Power Balance	N/A	Untested
Readings (check if	IN/A	Onlested
necessary)		
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger	N/A	
Air Cooler	IV/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator	Passed	Ok
Cap and Radiator Cooling Fans, Clutches		
and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise	Deced	Ok
Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL		
SYSTEM Starter Operation	Dagged	Ok
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.48 v
Alternator Output	Passed	13.34 v
Diesel Glow Plug System	N/A	Gasoline Engine
UNDER CHASSIS	35	
PASSED	29	
REPAIR	1	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM	. 40004	
Exhaust System		
Condition	N/A	Untested
Emissions Control Test	N/A	Untested
TRANSMISSION,		
TRANSAXLE,		
DIFFERENTIAL AND TRANSFER CASE		
Automatic	Deces'	Ol.
Transmission/Transaxle	Passed	Ok
Transmission/Transaxle	1 40304	JK.

Manual		
Manual Transmission/Transaxle		
, Differential and	N/A	Automatic Transmission
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV	14/7 (
Joints and CV Joint	Passed	Ok
Boots	rasseu	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	1 43364	OK
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS	1 40004	OK .
Tires Match and Are	Passed	185/60R15
Correct Size		
Wheels Match and Are Correct Size	Passed	Ok
Tire Tread Depth –		
Front Tires (L/R)	Passed	5mm
Tire Tread Depth –		
Rear Tires (L/R)	Passed	5mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front		00 :
Tires (L/R)	Passed	30 psi
Tire Pressure – Rear	Danad	20
Tires (L/R)	Passed	32 psi
Tire Pressure	NI/A	
Monitoring System	N/A	
No Evidence of Wheel	Repair	All Mags (Scratches)
Curb Damage	Repail	All Mays (Scratches)
Wheel Covers and	Passed	Ok
Center Caps	1 83360	OK .
Rack-and-Pinion,	Passed	Ok
Linkage and Boots	1 40004	O.K
Control Arms, Bushings	Passed	Ok
and Ball Joints		OK .
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and	Passed	Ok
Bushings		
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)		
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel	Passed	Ok
Cylinders	1 03300	OK.
Brake Pads and Shoes	Passed	Ok
Front Brakes (L/R)	. 40004	
Brake Pads and Shoes	Passed	Ok
– Rear Brakes (L/R)		
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Passed	Ok
and Fittings		
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK