| | Client / Company Name | Kotse Network Quezon Ave Ian Broqueza |
|--------------------------------|-------------------------|--|
| | Year / Make / Model | TOYOTA FJ CRUISER 2015 |
| | Plate / Conduction | ABF 9201 |
| | Price | 1.630 M neg. |
| | Transmission | Automatic Transmission |
| Carmudi | Mileage(Kms) | 12,893 km. |
| Inspection | Date Inspected | July 9, 2018 |
| Form | Mechanic Name | JR VISANDE |
| | Total Passed | 142 |
| | Total for Repair | 0 |
| | Total for Replacement | 0 |
| | Total N/A | 30 |
| | Total Inspection Points | 172 |
| | | |
| EXTERIOR | 38 | |
| PASSED | 33 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 5 | |
| BODY PANELS AND BUMPERS | | |
| No Evidence of Flood Damage | Passed | Cleared |
| No Evidence of Fire Damage | Passed | Cleared |
| No Evidence of Major Damage | Passed | Cleared |
| No Evidence of Hail Damage | Passed | Cleared |

| Body Panel Inspection | Passed | Ok |
|---|--------|----|
| Bumper/Fascia Inspection | Passed | Ok |
| Faded Paint | Passed | Ok |
| Different Shade / Color Panel | Passed | Ok |
| Different size panel gaps | Passed | Ok |
| Loose or missing trim pieces | Passed | Ok |
| Evidence of poorly repaired accident damage | Passed | Ok |
| Small rust spots | Passed | Ok |
| DOORS, HOOD, DECKLID, TAILGATE | | |
| Doors Inspection/Alignment | Passed | Ok |
| Hood Inspection/Alignment | Passed | Ok |
| Decklid Inspection/Alignment | N/A | |
| Tailgate Inspection/Alignment | Passed | Ok |
| Roof Inspection | Passed | Ok |
| Hood Release Mechanisms Operate Properly | Passed | Ok |
| Hood Hinges Operate Properly | Passed | Ok |
| Hood Prop Rod/Gas Struts Operate Properly | Passed | Ok |
| Door Hinges Operate Properly | Passed | Ok |
| Trunk/Tailgate Hinges/Gas Struts Operate Properly | Passed | Ok |
| GRILLE, TRIM AND ROOF RACK | | |
| Grille Inspection | Passed | Ok |
| Trim Inspection | Passed | Ok |

| Dest Dest Leaves (fee | NI/A | |
|---------------------------------------|--------|-----------------------|
| Roof Rack Inspection | N/A | |
| Deployable Running Boards | N/A | |
| GLASS AND OUTSIDE MIRRORS | | |
| Windshield Glass Inspection | Passed | Ok |
| Side Glass Inspection | Passed | Ok |
| Rear Window/Tailgate Glass Inspection | Passed | Ok |
| Wiper Blade Replacement | Passed | Ok |
| Outside Mirror Inspection | Passed | Ok |
| Outside Folding Mirror Inspection | Passed | Ok |
| EXTERIOR LIGHTS | | |
| Front-End Exterior Lights | Passed | Ok |
| Back-End Exterior Lights | Passed | Ok |
| Side Exterior Lights | Passed | Ok |
| Hazard Lights | Passed | Ok |
| Auto On/Off Lighting | N/A | |
| Trailer Lamp Connector Operation | N/A | |
| INTERIOR | 63 | |
| PASSED | 46 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 17 | |
| CONVENIENCE | | |
| Owner's Guide | Passed | Ok |
| Keys and Remote Controls | Passed | Ok |
| AIRBAG AND SAFETY BELTS | | |
| Airbags | Passed | With Passenger Airbag |

| Safety Belts | Passed | Ok |
|--|--------|----|
| AUDIO AND ALARM SYSTEMS | | |
| Radio, Cassette, CD and Speakers | Passed | Ok |
| Antenna | Passed | Ok |
| Alarm/Theft-Deterrent System | Passed | Ok |
| Navigation System | N/A | |
| HEAT/VENT/AC/DEFO G/DEFROST | | |
| Air Conditioning System | Passed | Ok |
| Heating System | Passed | Ok |
| Defog/Defrost | Passed | Ok |
| INTERIOR AMENITIES | | |
| Clock | Passed | Ok |
| Tilt/Telescopic Steering Wheel | Passed | Ok |
| Steering Column Lock | Passed | Ok |
| Steering Wheel Controls | Passed | Ok |
| Horn | Passed | Ok |
| Warning Chimes | Passed | Ok |
| Instrument Panel and Warning Lights | Passed | Ok |
| Windshield Wipers | Passed | Ok |
| Rear Window Wiper | Passed | Ok |
| Washers | Passed | Ok |
| Interior Courtesy, Dome and Map Lights | Passed | Ok |
| Outside Rearview Mirrors | N/A | |
| Auto-Dimming Rearview Mirror | Passed | Ok |
| Rear View Camera System) | N/A | |
| Active Park Assist | Passed | Ok |

| Rear Entertainment System | N/A | |
|---|--------|----|
| Power Outlets | Passed | Ok |
| Lighter | Passed | Ok |
| Ashtrays | Passed | Ok |
| Glove Box | Passed | Ok |
| Center Armrest/Console | Passed | Ok |
| Sun Visors, Vanity Mirror and Light | Passed | Ok |
| Adjustable Pedals (if equipped) | N/A | |
| CARPET, TRIM AND MATS | | |
| Interior Odor-Free | Passed | Ok |
| Carpet | Passed | Ok |
| Floor Mats | Passed | Ok |
| Door Trim and Door Panels | Passed | Ok |
| Headliner | Passed | Ok |
| SEATS | | |
| Seat Upholstery | Passed | Ok |
| Seat and Head Restraint Adjustment | Passed | Ok |
| Folding Seats | Passed | Ok |
| Heated Seats | N/A | |
| Cooled Seats | N/A | |
| Integrated Child Safety Seats | N/A | |
| SUNROOF/MOONRO OF/CONVERTIBLE TOP | | |
| Sunroof/Moonroof | N/A | |
| Convertible Top | N/A | |
| WINDOWS AND DOOR LOCKS | | |
| Door Handles and Release Mechanisms | Passed | Ok |

| Push-Button Start System Door Locks Passed Ok Child Safety Locks Passed Ok Window Controls Remote Decklid Release Fuel Filler Door Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A Ok Ok Ok Ok Ok Ok Ok Ok Ok O | 5 , 5 , 6 , | 5 . | 01 |
|---|---------------------------------|--------|---------|
| System Door Locks Passed Ok Child Safety Locks Passed Ok Window Controls Remote Decklid Release Fuel Filler Door Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Ok | Remote Entry System | Passed | Ok |
| Child Safety Locks Window Controls Remote Decklid Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Ok N/A N/A N/A Ok Ok Ok Ok Ok Ok Ok Ok Ok O | | N/A | |
| Window Controls Remote Decklid Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Ok N/A N/A N/A Ok Ok Ok Ok Ok Ok Ok Ok Ok O | Door Locks | Passed | Ok |
| Remote Decklid Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A N/A Ok Passed Ok | Child Safety Locks | Passed | Ok |
| Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure InvA Passed Ok | Window Controls | Passed | Ok |
| Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Passed OK N/A N/A ANA ANA ANA ANA ANA AN | Release | N/A | |
| COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A N/A Ok Passed Ok | Release | Passed | Ok |
| Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A N/A N/A Ok Passed Ok | | | |
| Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A N/A N/A Ok Passed Ok | | | |
| Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A Ok Passed Ok Ok Ok Ok Ok | Carpet | N/A | |
| Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection N/A Passed Ok Ok Passed Ok Ok Ok | Trim and Cargo Net | N/A | |
| Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Passed Ok Ok Ok Ok | Compartment/Cargo Area Light | N/A | |
| and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Passed Ok Ok Ok Ok Ok Ok Ok Ok Ok O | Early Warning Device | Passed | Ok |
| Depth/Air Pressure Passed Ok Inspection | | Passed | Ok |
| Tire Inflator Kit N/A | Depth/Air Pressure | Passed | Ok |
| THE HILIATOR INC. | Tire Inflator Kit | N/A | |
| Emergency Trunk-Lid Release N/A | | N/A | |
| DIAGNOSTICS 1 | DIAGNOSTICS | 1 | |
| PASSED 1 | PASSED | 1 | |
| REPAIR 0 | REPAIR | 0 | |
| REPLACEMENT 0 | REPLACEMENT | 0 | |
| N/A 0 | N/A | 0 | |
| MODULE SYSTEM TEST | | | |
| Perform Self-Test for all CMDTCs Passed Cleared | | Passed | Cleared |
| UNDERHOOD 35 | UNDERHOOD | 35 | |

| PASSED | 31 | |
|--|------------|------------------------|
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 4 | |
| FLUIDS | | |
| Engine Oil/Filter Change | Passed | Ok |
| Coolant | Passed | Ok |
| Brake Fluid | Passed | Ok |
| Automatic Transaxle/Transmission Fluid | Passed | Ok |
| Transfer Case Fluid | Passed | Ok |
| Drive Axle Fluid | Passed | Ok |
| Power Steering Fluid | Passed | Ok |
| Manual Transaxle/Transmission Hydraulic Clutch Fluid | N/A | Automatic transmission |
| Washer Fluid | Passed | Ok |
| ENGINE | | |
| Fluid Leaks | Passed | Ok |
| Hoses, Lines and Fittings | Passed | Ok |
| Belts | Passed | Ok |
| Wiring | Passed | Ok |
| Oil in Air Cleaner Housing | Passed | Ok |
| Water, Sludge or Engine Coolant in Oil | Passed | Ok |
| Oil Pressure | Passed | Ok |
| Relative Cylinder Compression | | |
| Test/Power Balance Readings (check if necessary) | N/A | Untested |
| Test/Power Balance Readings (check if | N/A N/A | Untested Untested |

| Inspect Turbocharger Air Cooler | N/A | |
|--|--------|---------------|
| COOLING SYSTEM | | |
| Radiator | Passed | Ok |
| Pressure-Test Radiator Cap and Radiator | Passed | Ok |
| Cooling Fans, Clutches and Motors | Passed | Ok |
| Water Pump | Passed | Ok |
| Coolant Recovery Tank | Passed | Ok |
| Cabin Air Filter | Passed | Cleaning only |
| FUEL SYSTEM | | |
| Fuel Pump Noise Normal | Passed | Ok |
| Fuel Pump Pressure | Passed | Ok |
| Fuel Filter | Passed | Ok |
| Engine Air Filter | Passed | Cleaning only |
| ELECTRICAL SYSTEM | | |
| Starter Operation | Passed | Ok |
| Ignition System | Passed | Ok |
| Battery | Passed | 12.51 v |
| Alternator Output | Passed | 13.80 v |
| Diesel Glow Plug System | Passed | Ok |
| UNDER CHASSIS | 35 | |
| PASSED | 31 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 4 | |
| FRAME | | |
| Frame Damage | Passed | Ok |
| Fuel Supply System | Passed | Ok |
| EXHAUST SYSTEM | | |
| Exhaust System Condition | N/A | |

| Emissions Control Test | N/A | |
|---|--------|------------------------|
| TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE | | |
| Automatic Transmission/Transaxle | Passed | Ok |
| Manual Transmission/Transaxle , Differential and Transfer Case | N/A | Automatic transmission |
| 4x4 Hub Operation | Passed | Ok |
| Universal Joints, CV Joints and CV Joint Boots | Passed | Ok |
| Transmission Mounts (not cracked, broken or oil-soaked) | Passed | Ok |
| Differential/Drive Axle | Passed | Ok |
| TIRES AND WHEELS | | |
| Tires Match and Are Correct Size | Passed | 265/70R17 |
| Wheels Match and Are Correct Size | Passed | Ok |
| Tire Tread Depth – Front Tires (L/R) | Passed | 4mm |
| Tire Tread Depth – Rear Tires (L/R) | Passed | 4mm |
| Normal Tire Wear | Passed | Normal |
| Tire Pressure – Front Tires (L/R) | Passed | 30 psi |
| Tire Pressure – Rear Tires (L/R) | Passed | 32 psi |
| Tire Pressure Monitoring System | N/A | |
| No Evidence of Wheel Curb Damage | Passed | Ok |
| Wheel Covers and Center Caps | Passed | Ok |
| Rack-and-Pinion, Linkage and Boots | Passed | Ok |

| Control Arms, Bushings and Ball Joints | Passed | Ok |
|--|--------|-----------------------|
| Tie Rods and Idler Arm | Passed | Ok |
| Sway Bars, Links and Bushings | Passed | Ok |
| Springs | Passed | Ok |
| Struts and Shocks | Passed | Ok |
| Wheel Alignment (check if necessary) | Passed | Ok Based on Tire Wear |
| Power Steering Pump | Passed | Ok |
| BRAKES | | |
| Calipers and Wheel Cylinders | Passed | Ok |
| Brake Pads and Shoes – Front Brakes (L/R) | Passed | Ok |
| Brake Pads and Shoes – Rear Brakes (L/R) | Passed | Ok |
| Rotors and Drums | Passed | Ok |
| Brake Lines, Hoses and Fittings | Passed | Ok |
| Parking Brake | Passed | Ok |
| Master Cylinder and Booster | Passed | Ok |