	Client / Company Name	OLF Auto Center-Othello
	Year / Make / Model	Fuentabella 2012 TOYOTA FORTUNER G
	Plate / Conduction	TQM 522
	Price	868 K
	Transmission	Automatic Transmission
Carmudi	Mileage(Kms)	60119
Inspection	Date Inspected	May 18, 2018
Form	Mechanic Name	Ralfh Gata
	Total Passed	138
	Total for Repair	1
	Total for Replacement	1
	Total N/A	32
	Total Inspection Points	172
EXTERIOR	38	
PASSED	34	
REPAIR	0	
REPLACEMENT	0	
N/A	4	
BODY PANELS AND BUMPERS		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok

DOORS, HOOD,		
DECKLID, TAILGATE		
Doors		01
Inspection/Alignment	Passed	Ok
Hood	Passed	Ok
Inspection/Alignment	1 43304	OR .
Decklid	Passed	Ok
Inspection/Alignment Tailgate		
Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release	1 43304	OK .
Mechanisms Operate	Passed	Ok
Properly		
Hood Hinges Operate	Passed	Ok
Properly	1 83360	OR .
Hood Prop Rod/Gas	Passed	Ok
Struts Operate Properly		
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate		
Hinges/Gas Struts	Passed	Ok
Operate Properly		
GRILLE, TRIM AND		
ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running	Passed	Ok
Boards	1 83360	OR .
GLASS AND OUTSIDE		
MIRRORS Windshield Glass		
Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate		
Glass Inspection	Passed	Ok
Wiper Blade	Passed	Ok
Replacement	rasseu	OK .
Outside Mirror	Passed	Ok
Inspection		- 17
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior		
Lights	Passed	Ok
Back-End Exterior	Dagged	Ok
Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector		
Operation	N/A	
INTERIOR	63	
PASSED	44	

REPAIR	0	
REPLACEMENT	0	
N/A	19	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	Passed	Ok
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
•		
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread Depth/Air Pressure	Passed	Ok
Inspection	Passeu	OK
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR		
REPLACEMENT	1	
N/A	4	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic Transmission
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner	Passed	Ok
Water, Sludge or	Passed	Ok
Engine Coolant in Oil		
Oil Pressure	Passed	Ok

Relative Cylinder		
Compression Test/Power Balance	N/A	Untested
Readings (check if	IV/A	Ontested
necessary)		
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger	N/A	
Air Cooler	1 1// 1	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches		
and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Replace	Dirty Cabin Filter need to Replace
FUEL SYSTEM		
Fuel Pump Noise	Passed	Ok
Normal		
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Repair	Cleaning Only
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.58 v
Alternator Output	Passed	13.89 v
Diesel Glow Plug	Passed	Ok
System		OK
UNDER CHASSIS	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System	N/A	Untested
Condition		
Emissions Control Test	N/A	Untested
TRANSMISSION, TRANSAXLE,		
DIFFERENTIAL AND		
TRANSFER CASE		
Automatic	Passed	Ok
Transmission/Transaxle		-

Manual		
Manual Transmission/Transaxle		
, Differential and	N/A	Automatic Transmission
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV	14/71	
Joints and CV Joint	Passed	Ok
Boots	rasseu	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	1 45564	OK
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS	1 43304	OK .
Tires Match and Are	Passed	265/65R17
Correct Size		
Wheels Match and Are	Passed	Ok
Correct Size Tire Tread Depth –		
	Passed	5mm
Front Tires (L/R) Tire Tread Depth –		
Rear Tires (L/R)	Passed	5mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front		
Tires (L/R)	Passed	30 psi
Tire Pressure – Rear	Desert	20
Tires (L/R)	Passed	32 psi
Tire Pressure	N/A	
Monitoring System	IN/A	
No Evidence of Wheel	Passed	Ok
Curb Damage	rasseu	OK
Wheel Covers and	Passed	Ok
Center Caps	1 43304	
Rack-and-Pinion,	Passed	Ok
Linkage and Boots	. 2000	<u> </u>
Control Arms, Bushings	Passed	Ok
and Ball Joints		
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and	Passed	Ok
Bushings		
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)		
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel	Passad	Ok
Cylinders	Passed	Ok
Brake Pads and Shoes	Passed	Ok
Front Brakes (L/R)	1-099CU	OK
Brake Pads and Shoes	Passed	Ok
- Rear Brakes (L/R)	1- a335U	OK
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Passed	Ok
and Fittings	1- asseu	OK .
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK