	Client / Company Name	Chin Ugarte
	Year / Make / Model	2014 MITSUBISHI MONTERO SPORT GLX
	Plate / Conduction	AAV 9255
	Price	878 K Negotiable
	Transmission	Automatic Transmission
Carmudi	Mileage(Kms)	37398 km
Inspection	Date Inspected	May 9, 2018
Form	Mechanic Name	Ralfh Gata
	Total Passed	138
	Total for Repair	2
	Total for Replacement	0
	Total N/A	32
	Total Inspection Points	172
EXTERIOR	38	
PASSED	32	
REPAIR	2	
REPLACEMENT	0	
N/A	4	
BODY PANELS AND BUMPERS		
No Evidence of Flood	Decemb	Oleaned
Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Repair	Front Bumper(Scratches)
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok

DOORS, HOOD,		
DECKLID, TAILGATE		
Doors Inspection/Alignment	Repair	Front Door Driver and Passenger and Rear Passenger Left Door (Scratched and Dent)
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	Passed	Ok
Tailgate Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running Boards	Passed	Ok
GLASS AND OUTSIDE MIRRORS		
Windshield Glass Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	

PASSED	45	
REPAIR	0	
REPLACEMENT	0	
N/A	18	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote	Passed	Ok
Controls AIRBAG AND SAFETY	1 0000	
BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO		
G/DEFROST Air Conditioning		
System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok

Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center		
Armrest/Console	Passed	Ok
Sun Visors, Vanity	Passed	Ok
Mirror and Light		
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND		
MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head	Passed	Ok
Restraint Adjustment		
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO		
OF/CONVERTIBLE		
ТОР		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND		
DOOR LOCKS Door Handles and		
Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start	N/A	
System		
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid	N/A	
Release Fuel Filler Door		
Release	Passed	Ok
LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment	N/A	
Trim and Cargo Net		

Luggage	N1/A	
Compartment/Cargo	N/A	
Area Light Vehicle Jack, Tool Kit,		
Early Warning Device	Passed	Ok
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	Passed	Ok
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	Passed	Ok
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	N/A	Automatic Transmission
Washer Fluid		
	Passed	Ok
ENGINE	Passed	Ok
Fluid Leaks	Passed	Ok
Fluid Leaks Hoses, Lines and Fittings		Ok Ok
Fluid Leaks Hoses, Lines and	Passed	Ok
Fluid Leaks Hoses, Lines and Fittings Belts Wiring	Passed Passed	Ok Ok
Fluid Leaks Hoses, Lines and Fittings Belts	Passed Passed Passed	Ok Ok Ok

Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.57 v
Alternator Output	Passed	13.47 v
Diesel Glow Plug System	Passed	Ok
UNDER CHASSIS	35	
PASSED	30	
REPAIR	0	
REPLACEMENT	0	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	Untested
Emissions Control Test	N/A	Untested
TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE		
Automatic Transmission/Transaxle	Passed	Ok

Manual		
Manual Transmission/Transaxle		
, Differential and	N/A	Automatic Transmission
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV	14/71	
Joints and CV Joint	Passed	Ok
Boots	rasseu	OK
Transmission Mounts		
(not cracked, broken or	Passed	Ok
oil-soaked)	1 45564	OK
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS	1 43304	OK .
Tires Match and Are	Passed	265/65R17
Correct Size		
Wheels Match and Are	Passed	Ok
Correct Size Tire Tread Depth –		
	Passed	5mm
Front Tires (L/R) Tire Tread Depth –		
Rear Tires (L/R)	Passed	5mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front		
Tires (L/R)	Passed	30 psi
Tire Pressure – Rear	Desert	20
Tires (L/R)	Passed	32 psi
Tire Pressure	N/A	
Monitoring System	IN/A	
No Evidence of Wheel	Passed	Ok
Curb Damage	rasseu	OK
Wheel Covers and	Passed	Ok
Center Caps	1 43304	
Rack-and-Pinion,	Passed	Ok
Linkage and Boots	. 2000	<u> </u>
Control Arms, Bushings	Passed	Ok
and Ball Joints		
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and	Passed	Ok
Bushings		
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)		
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel	Passad	Ok
Cylinders	Passed	Ok
Brake Pads and Shoes	Passed	Ok
<ul><li>Front Brakes (L/R)</li></ul>	1-099CU	OK
Brake Pads and Shoes	Passed	Ok
- Rear Brakes (L/R)	1- a335U	OK
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Passed	Ok
and Fittings	1- asseu	OK .
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK