

<b>Carmudi Inspection Form</b>	Client / Company Name	Axis Auto Network - Johnner Zuniga
	Year / Make / Model	2014 FORD EVEREST
	Plate / Conduction	AAQ 6835
	Price	768 K Negotiable
	Transmission	Manual Transmission
	Mileage(Kms)	59448 km
	Date Inspected	February 5, 2018
	Mechanic Name	Ralfh Gata
	Total Passed	139
	Total for Repair	0
	Total for Replacement	0
	Total N/A	33
	Total Inspection Points	172
<b>EXTERIOR</b>	38	
<b>PASSED</b>	34	
<b>REPAIR</b>	0	
<b>REPLACEMENT</b>	0	
<b>N/A</b>	4	
<b>BODY PANELS AND BUMPERS</b>		
No Evidence of Flood Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared

Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
<b>DOORS, HOOD, DECKLID, TAILGATE</b>		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid Inspection/Alignment	N/A	
Tailgate Inspection/Alignment	Passed	Ok
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
<b>GRILLE, TRIM AND ROOF RACK</b>		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok

Roof Rack Inspection	N/A	
Deployable Running Boards	Passed	Ok
<b>GLASS AND OUTSIDE MIRRORS</b>		
Windshield Glass Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
<b>EXTERIOR LIGHTS</b>		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
<b>INTERIOR</b>	63	
<b>PASSED</b>	44	
<b>REPAIR</b>	0	
<b>REPLACEMENT</b>	0	
<b>N/A</b>	19	
<b>CONVENIENCE</b>		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
<b>AIRBAG AND SAFETY BELTS</b>		
Airbags	Passed	With Passenger Airbag

Safety Belts	Passed	Ok
<b>AUDIO AND ALARM SYSTEMS</b>		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	N/A	
Navigation System	N/A	
<b>HEAT/VENT/AC/DEFOG/DEFROST</b>		
Air Conditioning System	Passed	Ok
Heating System	Passed	Ok
Defog/Defrost	Passed	Ok
<b>INTERIOR AMENITIES</b>		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	

Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
<b>CARPET, TRIM AND MATS</b>		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
<b>SEATS</b>		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
<b>SUNROOF/MOONROOF/CONVERTIBLE TOP</b>		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
<b>WINDOWS AND DOOR LOCKS</b>		
Door Handles and Release Mechanisms	Passed	Ok

Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door Release	Passed	Ok
<b>LUGGAGE COMPARTMENT</b>		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	
Vehicle Jack, Tool Kit, Early Warning Device	Passed	Lacking Early Warning Device
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	N/A	
<b>DIAGNOSTICS</b>	1	
<b>PASSED</b>	1	
<b>REPAIR</b>	0	
<b>REPLACEMENT</b>	0	
<b>N/A</b>	0	
<b>MODULE SYSTEM TEST</b>		
Perform Self-Test for all CMDTCs	Passed	Cleared
<b>UNDERHOOD</b>	35	

<b>PASSED</b>	30	
<b>REPAIR</b>	0	
<b>REPLACEMENT</b>	0	
<b>N/A</b>	5	
<b>FLUIDS</b>		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	N/A	Manual Transmission
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	Passed	Ok
Washer Fluid	Passed	Ok
<b>ENGINE</b>		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok

Inspect Turbocharger Air Cooler	N/A	
<b>COOLING SYSTEM</b>		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
<b>FUEL SYSTEM</b>		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
<b>ELECTRICAL SYSTEM</b>		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.84 v
Alternator Output	Passed	13.58v
Diesel Glow Plug System	Passed	Ok
<b>UNDER CHASSIS</b>	35	
<b>PASSED</b>	30	
<b>REPAIR</b>	0	
<b>REPLACEMENT</b>	0	
<b>N/A</b>	5	
<b>FRAME</b>		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
<b>EXHAUST SYSTEM</b>		
Exhaust System Condition	N/A	Untested



Emissions Control Test	N/A	Untested
<b>TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE</b>		
Automatic Transmission/Transaxle	N/A	Manual Transmission
Manual Transmission/Transaxle , Differential and Transfer Case	Passed	Ok
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Ok
<b>TIRES AND WHEELS</b>		
Tires Match and Are Correct Size	Passed	255/60R18
Wheels Match and Are Correct Size	Passed	Ok
Tire Tread Depth – Front Tires (L/R)	Passed	7mm
Tire Tread Depth – Rear Tires (L/R)	Passed	7mm
Normal Tire Wear	Passed	Normal
Tire Pressure – Front Tires (L/R)	Passed	30 psi
Tire Pressure – Rear Tires (L/R)	Passed	32 psi
Tire Pressure Monitoring System	N/A	
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion, Linkage and Boots	Passed	Ok

Control Arms, Bushings and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok Based on Tire Wear
Power Steering Pump	Passed	Ok
<b>BRAKES</b>		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes – Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes – Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok