	Client / Company Name	Auto Palace Sales Center - Jimmy
	Client / Company Name	Valdez
	Year / Make / Model	TOYOTA VIOS 1.3E AT 2018
	Plate / Conduction	A2 S085
	Price	550 K neg.
	Transmission	Manual Transmission
Carmudi	Mileage(Kms)	7,938 km.
Inspection	Date Inspected	May 21, 2018
Form	Mechanic Name	JR VISANDE
	Total Passed	133
	Total for Repair	1
	Total for Replacement	0
	Total N/A	38
	Total Inspection Points	172
EXTERIOR	38	
PASSED	32	
REPAIR	1	
REPLACEMENT	0	
N/A	5	
BODY PANELS AND BUMPERS		
No Evidence of Flood	December	Observe I
Damage	Passed	Cleared
No Evidence of Fire Damage	Passed	Cleared
No Evidence of Major Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok

DOORS, HOOD,		
DECKLID, TAILGATE		
Doors	Dagged	Ok
Inspection/Alignment	Passed	Ok
Hood	Passed	Ok
Inspection/Alignment	1 40004	O.K
Decklid	Repair	Trunk scratch
Inspection/Alignment Tailgate		
Inspection/Alignment	N/A	
Roof Inspection	Passed	Ok
Hood Release		
Mechanisms Operate	Passed	Ok
Properly		
Hood Hinges Operate	Passed	Ok
Properly		
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate	_	
Properly	Passed	Ok
Trunk/Tailgate		
Hinges/Gas Struts	Passed	Ok
Operate Properly		
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
Deployable Running Boards	N/A	
GLASS AND OUTSIDE		
MIRRORS		
Windshield Glass	Passed	Ok
Inspection	1 43304	OK .
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate	Passed	Ok
Glass Inspection		
Wiper Blade Replacement	Passed	Ok
Outside Mirror		2:
Inspection	Passed	Ok
Outside Folding Mirror	Passed	Ok
Inspection	1 43364	OK.
EXTERIOR LIGHTS		
Front-End Exterior	Passed	Ok
Lights		
Back-End Exterior Lights	Passed	Ok
Side Exterior Lights	Passed	Ok
Hazard Lights	Passed	Ok
		OK .
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	42	
TAGGLU	42	

REPAIR	0	
REPLACEMENT	0	
N/A	21	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	With Passenger Airbag
Safety Belts	Passed	Ok
AUDIO AND ALARM SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	Passed	Ok
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	N/A	
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	N/A	
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok

Ashtrays	Passed	Ok
•		
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start System	N/A	
Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid Release	N/A	
Fuel Filler Door	Passed	Ok
Release LUGGAGE		
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	

Vehicle Jack, Tool Kit,	Passed	Ok
Early Warning Device	1 43304	OK .
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok
Spare Tire Tread	Dagged	Ok
Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid	N/A	
Release		
DIAGNOSTICS	1	
PASSED	1	
REPAIR	0	
REPLACEMENT	0	
N/A	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	Passed	Cleared
UNDERHOOD	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	N/A	Manual Transmission
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Electronic type
Manual Transaxle/Transmission Hydraulic Clutch Fluid	Passed	Ok
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner		
Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok

Relative Cylinder Compression	<b></b>	
Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Passed	Ok
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.53 v
Alternator Output	Passed	13.57 v
Diesel Glow Plug System	N/A	Gasoline engine
UNDER CHASSIS	35	
PASSED	29	
REPAIR	0	
REPLACEMENT	0	
N/A	6	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	
Emissions Control Test	N/A	
TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE		
Automatic Transmission/Transaxle	N/A	Manual Transmission

Manage		
Manual Transmission/Transaxle		
, Differential and	Passed	Ok
Transfer Case		
4x4 Hub Operation	N/A	
· ·	IN/A	
Universal Joints, CV	Danad	O.L.
Joints and CV Joint	Passed	Ok
Boots		
Transmission Mounts	Danad	O.L.
(not cracked, broken or	Passed	Ok
oil-soaked)		
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are	Passed	185/60R15
Correct Size	1 83360	103/001(13
Wheels Match and Are	Passed	Ok
Correct Size	1 40004	OK .
Tire Tread Depth –	Passed	3mm
Front Tires (L/R)	1 40004	3.1.111
Tire Tread Depth –	Passed	3mm
Rear Tires (L/R)		-
Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	30 psi
Tires (L/R)	. 2000	об ро
Tire Pressure – Rear	Passed	32 psi
Tires (L/R)		- 1
Tire Pressure	N/A	
Monitoring System		
No Evidence of Wheel	Passed	Ok
Curb Damage		
Wheel Covers and	Passed	Ok
Center Caps		
Rack-and-Pinion,	Passed	Ok
Linkage and Boots		
Control Arms, Bushings and Ball Joints	Passed	Ok
	Passed	Ok
Tie Rods and Idler Arm	Passeu	Ok
Sway Bars, Links and	Passed	Ok
Bushings	December	
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment	Passed	Ok Based on Tire Wear
(check if necessary)		
Power Steering Pump	N/A	electronic type
BRAKES		
Calipers and Wheel	Doorad	Ole
Cylinders	Passed	Ok
Brake Pads and Shoes	Dagged	Oh
- Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes	Dascod	Ok
- Rear Brakes (L/R)	Passed	UK
Rotors and Drums	Passed	Ok
Brake Lines, Hoses	Dagged	Ok
and Fittings	Passed	Ok
Parking Brake	Passed	Ok

Master Cylinder and	Passed	Ok
Booster	rasseu	OK