Inspection Date:	March 2, 2025 | Time: 10:00 AM - 12:30 PM (2.5 hrs)
Property Address:	1438 Garden Terrace, Burnaby, BC V5A 3G2
Client:	Jane Marie Doe & John Robert Doe
Inspector:	Sarah J. Nakamura | Lic #: BC-RHI-08847
Weather Conditions:	Overcast, 8C, light rain earlier, dry during inspection

OVERALL ASSESSMENT: **GOOD CONDITION -- Minor Items Noted**

This townhouse is in good overall condition for its age (10 years). No major structural, safety, or mechanical deficiencies were identified.

1. ROOF & ATTIC

Roof Covering — SATISFACTORY

Roof in good condition, adequate useful life remaining.

Gutters & Downspouts — SATISFACTORY

Properly pitched, no leaks observed.

Attic Insulation — SATISFACTORY

Adequate insulation levels for climate zone.

2. EXTERIOR

Foundation (Visible) — SATISFACTORY

Foundation walls inspected -- no significant deficiencies.

Exterior Cladding — SATISFACTORY

Cladding in good condition overall.

Windows & Doors — SATISFACTORY

Windows operate properly, weatherstripping intact.

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.

SYNTHETIC DOCUMENT -- FOR DEMONSTRATION PURPOSES ONLY

3. INTERIOR -- STRUCTURE & FINISHES

Floors — GOOD

Flooring in good condition throughout.

Walls & Ceilings — SATISFACTORY

Painted drywall, minor cosmetic items only.

Doors (Interior) — GOOD

All doors latch and operate properly.

4. PLUMBING

Water Supply Lines — SATISFACTORY

Water pressure tested -- normal range. No evidence of leaks.

Drain, Waste & Vent — SATISFACTORY

All fixtures drain freely.

Hot Water Tank — SATISFACTORY

Hot water system functional.

5. HEATING & COOLING

Furnace / HVAC — GOOD

HVAC system operational.

Ductwork & Registers — SATISFACTORY

Ductwork in good condition.

6. ELECTRICAL

Electrical Panel — SATISFACTORY

Panel in good condition, properly labelled.

GFCI Protection — SATISFACTORY

GFCI outlets present and tested in all required locations.

Smoke & CO Detectors — SATISFACTORY

All detectors tested and operational.

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.

SYNTHETIC DOCUMENT -- FOR DEMONSTRATION PURPOSES ONLY

7. KITCHEN & BATHROOMS

Kitchen — GOOD

Kitchen in good condition.

Bathrooms — SATISFACTORY

All bathrooms functional.

8. SUMMARY OF FINDINGS

IMMEDIATE ACTION REQUIRED (None)

* None identified

MONITOR / BUDGET FOR FUTURE (2 item(s))

* Some exterior deck boards show weathering -- recommend sealing within 12 months (~$400-$600)
* One bathroom exhaust fan running slow -- clean or replace motor (~$80-$150)

MAINTENANCE NOTES (2 item(s))

* Annual HVAC servicing recommended -- currently up to date
* Recommend re-caulking exterior window perimeters during dry weather

INSPECTOR DECLARATION

I, Sarah J. Nakamura, Certified Home Inspector, confirm that this report was prepared following the Standards of Practice of CAHPI and represents my professional opinion based on conditions observed on the inspection date only. This report does not constitute a warranty or guarantee of any systems or components.

Sarah J. Nakamura Lic #BC-RHI-08847 | Date: March 2, 2025

This report is for the exclusive use of the named client. Inspector is not liable for defects discovered after date of inspection.

SYNTHETIC DOCUMENT -- FOR DEMONSTRATION PURPOSES ONLY