

AUTOMOTIVE REPAIR ESTIMATE

Shop Name: Greenfield Auto Body & Collision
Address: 4821 Industrial Blvd, Springfield, IL 62704
Phone: (217) 555-0194
Estimate Date: May 3, 2026
Estimate No: EST-2026-04471

Vehicle Information

Year / Make / Model: 2021 Honda Accord EX-L
VIN: 1HGCV1F34MA012345
Color: Lunar Silver Metallic
Mileage: 34,820 mi
Owner: Marcus J. Thornton
Claim ID: CLM-SMOKE-001

Damage Description

Vehicle sustained rear-end impact damage. Primary damage concentrated on front bumper fascia, hood leading edge, and radiator support. Airbags did not deploy. No structural frame damage detected.

Line Items

#	Description	Labor (hrs)	Parts (\$)	Labor (\$)	Total (\$)
1	Front bumper fascia — replace	2.5	485.00	187.50	672.50
2	Bumper reinforcement bar — replace	1.0	210.00	75.00	285.00
3	Hood — repair & repaint	4.0	120.00	300.00	420.00
4	Radiator support — straighten	2.0	0.00	150.00	150.00
5	Headlight assembly (L) — replace	0.5	395.00	37.50	432.50
6	Grille assembly — replace	0.5	185.00	37.50	222.50
7	Paint blend — adjacent panels	3.0	80.00	225.00	305.00
8	Alignment check post-repair	1.0	0.00	75.00	75.00

Subtotal	2,562.50
Tax (6.25%)	160.16
Shop Supplies	45.00

TOTAL 2,767.66

Estimator Notes

Estimate based on visual inspection only. Hidden damage may be discovered during repair. All parts OEM unless otherwise specified. Labor rate: \$75.00/hr. Estimate valid for 30 days.

Authorized Estimator: James R. Kowalski — License No. IL-AB-20471