Intervention Report

						N° commande	
Task Description: Ci	sco Switch repla	cement					
			Cus	tomer Informat	ion		
Site Contact	Santiago Bonnin						
Function				Adresse			
	1					C/Conradors 24, Marratxi	
Tel :				City		Marratxi	
Mobile :				Post Code		7	141
Day	Monday	Tuocday	Wednesday	Thursday	Friday		
Day Date	16-sep-24	Tuesday	vveuriesuay	Thursday	Filuay	+	-
Arrival Time (*)	10-sep-24 10:45						-
Departure Time (*)	10:43	1					_
beparture Time ()	12.43		ļ				
						Intervention Successful	
Work done and Observations (to be filled by Technici				ian)			
					Yes	NO	
Informed the site co had an issue with a d before the switch re the computer. Observations (To be	computer not co placement. We'v	nnecting to tl ve informed F	ne network. It hap	pened already	X		
Site Contact Name : Natalia				Name of Technician : Xavier Bennasar Mora			
Function : Administration				Function: Technician			
Date & signature + cachet				Date & signature			
				-			