



JOB SHEET

JS No. **14100**

Customer : **KPJ KLANG**

PO Ref Num :

Site : **KPJ KLANG**

Date : **28/4/2022**


WORK SCOPE:

☐ Repair ☐ Servicing ☐ Installation / Testing Commissioning ☐ Fire Drill / Bomba Inspection ☐ System Checking/Audit ☐ Fault Call

JOB DESCRIPTION

1. For - Datacentre room (chemetron) Level 1
 - Library / Medical / Record room (chemetron) Level 1
 - UPS Room (chemetron) Level 1
 - CT Scan room (chemetron) Level 1
 - Fluoroscopy room (chemetron) Level 1
 - Fluoroscopy control room (chemetron) Level 1
- a) Done supply labour, tools, equipment and material to perform hydrostatic test FM 200 cylinder include transfer existing agent into temporary storage, hydrostatic test for cylinder, transfer back agent into cylinder after hydrostatic, top up clean agent due to losses, leak test and pressurize FM 200 cylinder.
- b) Done replace cylinder valve oil seal.
- c) Done supply labour and tools to dismantle FM 200 cylinder for hydrostatic test and reinstall FM 200 cylinder after hydrostatic testing.


BY TECHNICIAN:

JOB STATUS		TECHNICIAN DETAILS		
<input type="checkbox"/> Completed	<input type="checkbox"/> Out of scope	Name	Rusainee, Fakhri, Faizel	
<input type="checkbox"/> Not Completed	<input type="checkbox"/> No Tools and spare parts	Date	28/4/2022	
<input type="checkbox"/> No Access	<input type="checkbox"/> Quotation to be provided	Signature		

BY CUSTOMER:

BY CUSTOMER:					
RATE OUR SERVICE		ACKNOWLEDGED / VERIFIED BY			
<input type="checkbox"/> Excellent	Name				
<input type="checkbox"/> Good	Date		Time		
<input type="checkbox"/> Average	Signature				
<input type="checkbox"/> Poor					

RUBBER STAMP



NAZARUDDIN B. MOHD ZIN
FACILITIES INCHARGE & ENGINEERING SERV
KPJ Klang Specialist Hospital
No 102, Persiaran Rajawali / Ku 1.

NAZARUDDIN B. MOHD ZIN
FACILITIES INCHARGE & ENGINEERING SERVICES
KPJ Klang Specialist Hospital
No 102, Persiaran Rajawali / Ku 1,
Bandar Baru Klang, 401150 Klang, Selangor
Email: nazaruddin@kpjklang.com.my
28/4/2022



JOB SHEET

JS No. **14099**

Customer : **KPJ KLANG**

PO Ref Num : _____

Site : **KPJ KLANG**

Date : **25/4/2022**

WORK SCOPE:

☐ Repair ☐ Servicing ☐ Installation / Testing Commissioning ☐ Fire Drill / Bomba Inspection ☐ System Checking/Audit ☐ Fault Call

JOB DESCRIPTION


A. **Genset Room.**

- complete refill 4 nos 45 kg CO₂ gas complete with leak test.
- complete refill 1 nos 2 kg CO₂ pilot cylinder.
- Done supply labour and tools to dismantle empty of 45 kg CO₂ cylinder with 2 kg pilot cylinder and install back after refilling complete with transportation.

B. **Fluoroscopy room**

- Done supply and install twin discharge light.

BY TECHNICIAN:

JOB STATUS		TECHNICIAN DETAILS			
<input type="checkbox"/> Completed	<input type="checkbox"/> Out of scope	Name	RUSANEE, FAKRI, FAICAL		Time In
<input type="checkbox"/> Not Completed	<input type="checkbox"/> No Tools and spare parts	Date	25/4/2022		Time out
<input type="checkbox"/> No Access	<input type="checkbox"/> Quotation to be provided	Signature			

BY CUSTOMER:

RATE OUR SERVICE		ACKNOWLEDGED / VERIFIED BY				RUBBER STAMP	
<input type="checkbox"/> Excellent		Name				 NAZARUDDIN B. MOHD ZIN FACILITIES INCHARGE & ENGINEERING SERVICES KPJ Klang Specialist Hospital No 102, Persiaran Rajawali / Ku 1, Bandar Baru Klang, 401150 Klang, Selangor Email: nazaruddin@kpjklang.com	
<input type="checkbox"/> Good		Date		Time			
<input type="checkbox"/> Average		Signature					
<input type="checkbox"/> Poor							

Customer copy
25/4/2022