

REMOVED DISTRIBUTION EQUIPMENT INSPECTION REPORT

AREA:		DIV.:		S/S #	
USER MDR #		S-		SERIAL #	
SEC # : 5666289		Equipment :		Year of manufacture :	
Make :		Prim / Sec.Volt :		Capacity (KVA) :	
UDS NO. 123456789					
☐ Oil leaks (specify) :				☒ Burnt / Melted Parts	
☐ Cracked / Chipped bushing HV () ea. LV () ea.				☐ Bulged / Corroded Body	
☐ Broken / Missing accessories(specify) :					
		REASONS FOR REMOVEAL			
☐ System Reinforcement		☒ System improvement		☐ Suspected defective / Defective	
☐ Damaged by SEC contractor	☐ Damaged by others	☐ Partially/totally damaged		☐ Non Standard	
☐ Others		Commissioning Data :		Removal / Failure Date :	
		USER'S RECOMMENDATION			
☐ REQUESTED FOR FUTURE	☐ WARRANTY	☐ REPAIRABLE	☒ RECOMMENDED FOR SCRAP		
☐ COMMENTS :					
Prepared by :		Approved by :		Date :	
WORKSHOP ACTION					
WORKSHOP	☐ Partially Damaged	☐ Totally Damaged		☐ Severely Rusted	
DIVISION	☐ Uneconomical to Repair	☐ REPAIRABLE		☒ SCRAP	
	COMMENTS :				
WAREHOUSE					
Prepared by :		Approved by :		Date	

	☐ REPAIRABLE			☐ SCRAP / SALE				
INVENTORY	☐ Standard Item	☐ Substitute	☐ Non standard	☐ Non Moving				
PLANNING	☐ Fast moving	☐ Others	☐ Over Stocking	☐ Damaged				
DEPARTMENT	Availability:	01:___	02:___	05:___	07:___	08:___	Sub. ___	Total: _____
	3 Year Usage :	12 : _____		13 : _____		Current : _____		
IPD	Comments :							
Prepared by :		Approved by :		Date :				