



MU YAR KHIN

Civil Engineer | Assistant Building Surveyor | QA/QC Engineer | Site Engineer

CONTACT



+959791623821(WhatsApp)



muyarkhin542@gmail.com



Yangon, Myanmar



<https://www.linkedin.com/in/muyarkhin542>

PERSONAL INFO

Date of Birth October 9th

Nationality Myanmar

Marital Status Single

Availability Immediate

Salary Negotiable

Visa Status Seeking
employer

//SKILLS

- Structural Inspection & Condition Assessment
- Seismic / Earthquake Vulnerability Assessment
- Defect Mapping & Technical Documents
- Non-Destructive Testing (NDT: Rebound Hammer, UPV)
- Building Surveying & Heritage Conservation
- Quality Control & Assurance (QA/QC)
- Project Coordination & Community Engagement
- AutoCAD, Advanced Excel, Microsoft Office
- Revit (In progress – building modeling skills)

SUMMARY

Civil Engineer with 13+ years of experience in structural inspection, building condition assessment, site supervision, heritage conservation, and QA/QC. Experienced in seismic vulnerability assessments, post-earthquake damage inspections, Non-Destructive Testing (NDT), and construction site management. Skilled in technical reporting, project coordination, document control, and ensuring quality and safety compliance throughout project execution. Seeking opportunities to contribute my expertise in building surveying, structural inspection, site engineering, and infrastructure projects.

PROFESSIONAL EXPERIENCE



Executive Engineer (2015 – 2025)

Special Project Committee, Federation of Myanmar Engineering Societies (Fed.MES)

- Conducted structural inspections, condition assessments, and Rapid Visual Screening (RVS) for **50+ public and heritage buildings**, including schools and hospitals.
- Led a team of **10 engineers** to assess **200+ heritage monuments** after the 2016 Chauk earthquake.
- Performed **NDT (Rebound Hammer & UPV)** and recommended repair and rehabilitation methods.
- Prepared technical reports, defect mapping, and restoration documentation for heritage buildings.
- Coordinated multidisciplinary teams and contributed to the **Myanmar National Building Code (MNBC)**.
- Managed quality control and document control for multiple construction and restoration projects.



Quantity Surveyor / Senior Engineer (2013 – 2015)

ABC Telecomm Co., Ltd.

- Prepared quantity take-offs, BOQs, and cost estimates for civil and telecom infrastructure projects.
- Assisted with tender preparation, budgeting, and cost control throughout project execution.
- Coordinated with contractors, subcontractors, and clients to resolve technical and site issues.
- Monitored project progress and supported timely project delivery.

Site Engineer (2012 – 2013)

Sub-Construction Co., Ltd.

- Supervised construction of a **6-story residential building (57,600 sq. ft)**.
- Directed finishing works including plastering, flooring, ceiling, and painting.
- Managed site operations, labor, materials, and subcontractors.
- Coordinated with MEP teams, ensuring site safety and quality control throughout the project.

//PROFESSIONAL CERTIFICATIONS & TRAINING

- 2020
ASEAN ENGINEER - 9180
ASEAN FEDERATION OF ENGINEERING ORGANIZATION
- 2018
ASSOCIATE ASEAN ENGINEER - 9062
ASEAN FEDERATION OF ENGINEERING ORGANIZATION
- 2019
SOLIDSWORKS PROGRAM
DEPARTMENT OF SKILL DEVELOPMENT MINISTRY OF LABOR (THAILAND)
- 2018
DISASTER MANAGEMENT
DEPARTMENT OF DISASTER MANAGEMENT
- 2019
EMERGENCY MEDICAL RESPONDER TRAINING
THE ROTARY FOUNDATION

// EDUCATION



Bachelor of Engineering (Civil)
Technological University
Yangon, Hmawbi, Myanmar
2012



**Bachelor of Science
(Mathematics)**
**Yangon University of Distance
Education**
Yangon, Myanmar
2012

// LANGUAGES

English	Professional Working Proficiency
Mandarin	
Chinese	(Beginner- current studying)
Myanmar	Native

// PROJECTS



Structural inspection and HSI checklist for JiWiTaDarNa hospital



Structural inspection and technical report - archaeological museum (Bagan)



Defect mapping - government telegraph office



Structural inspection and technical report for Shwe Nat Taung pagoda



Quality control for staff housing



NDT testing – fire damaged Than market