



Underclearance Record

Form 2601
(03/16)
Page 1 of 1

District: 02 County: 220 Control - Section: 0747 - 04 Structure #: 046 Route: Center Pedestrian Bridge
Feature Crossed: FM-157 Inspector's Signature: Karen McGill Date: 4/14/2024
Company Name and Company Number: Srinteg Corporation [F-20066]

Underclearance Record Sketch												
Place an "X" at the location of minimum vertical under-clearances on the sketch												

Controlling Item No.:	54.2 - Min. Vertical Clearance	10 or 10A - Max. 10' Wide Vertical Clearance	55.2 - Right Lateral Clearance	56 - Left Lateral Clearance	47 or 47A - Total Horizontal Clearance
-----------------------	--------------------------------	--	--------------------------------	-----------------------------	--

Reference Features:					
A. Beam	C. Cap	E. Guard fence	G. Pile	I. Toe of >3:1 Slope	K. Middle of Yellow Stripe
B. Slab	D. Railing	F. Column	H. Curb	J. Barrier	L. Middle of White Stripe
					M. Retaining Wall
					N. Pavement

Feature Xed →												
PSN:	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.
Right Lateral Clearance	6.5'	L-M	55.2									
Left Lateral Clearance	0	-	-									
Total Horizontal Clr	78.9'	M-M	47									
Max Practical Vert Clr	19'2"	A-N	10									
Min Measured Vert Clr	19'2"	A-N	54.2									
Signed Vertical Clr	17'10"	1'4"	Tolerance			Tolerance			Tolerance			Tolerance

PSN:	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.	Field Data	Refer.	Item No.
Right Lateral Clearance												
Left Lateral Clearance												
Total Horizontal Clr												
Max Practical Vert Clr												
Min Measured Vert Clr												
Signed Vertical Clr			Tolerance			Tolerance			Tolerance			Tolerance

