

SMMO / FWEE / 242

Dated 16/05/202

To whom it may concern

It is certified that inspection of Holy Family Convent School
Reg. No. 40821 was done by me and health team. It was found
satisfactory. The school building is good and having all proper hygienic
arrangements. The school is situated in pollution free environment.

Provision of Ieterin Ventilations etc. is good and airy. The
Provision of water supply is good with RO system. Stair properly cover
with Railing. Electricity wire proper Maintains.

Team visited on
dated 10/5/23

- (1) ~~Total~~ School Area Building - 27991 sq.m
- (2) ~~Total~~ Rooms - 74
- (3) Electricity Conditions - Good
- (4) Water Supply Source - Water Purifier / RO's
- (5) Toilet Condition - Boys 31, Girls 32, Neat and Clean
- (6) Fire safety system - Yes
- (7) Play Ground - 20769 sq.m
- (8) Conference Hall - 3
- (9) Sign Board - (Display Board with Registration) - Yes
- (10) Hand Washing Area - Available
- (11) Emergency Exit Gate - Yes, 4

Sangeeta Kumar
Senior Medical Officer
Civil Hospital Gohana