CERTIFICATE OF COMPLIANCE



Declares that the following analyzer:

Product Name:	Multi-gas Carbon Emissions CO/CO ₂ /CH ₄ /H ₂ O Analyzer - EP
Model Number:	909-0043-0000-0000
Serial Number:	3K60180500005016

Has been extensively tested and shown to meet all of the specifications listed in this document and is warranted for 1 year if used according to the instructions provided in the User's Manual.

CO/CO₂/CH₄/H₂O:

Measurement Range (100 seconds):	CO: 0.05 - 1000 ppm CO ₂ : 0.1 - 3000 ppm CH ₄ : 0.3 ppb - 100 ppm H ₂ O: 20 ppm – 98% RH		
Operational Range (external cal. may be required):	CO: 0 - 1% CO ₂ : 0 - 3% CH ₄ : 0 - 0.1% H ₂ O: 0 - 100% RH		
Repeatability / Precision (1-sigma):	CO: 0.12 ppm (1 sec), 0.02 ppm (100 sec) CO ₂ : 0.3 ppm (1 sec), 0.04 ppm (100 sec) CH ₄ : 2 ppb (1 sec), 0.3 ppb (100 sec) H ₂ O: 100 ppm (1 sec), 15 ppm (100 sec)		
Response Time (flow time through meas. cell):	20 s (with standard internal pump), < 2 s (with optional external vacuum pump)		
Outputs:	Digital (RS-232), Analog, Ethernet, USB		
Data Storage:	Internal Hard Disk Drive (optional Solid State Drive)		
Operating Temperature:	0 to 45 °C (Enhanced Performance)		
Inlet / Outlet Fittings:	1/4", and 3/8" Swagelok®		
Power Requirements:	115/230 VAC; 50/60 Hz, 150 W (Enhanced Performance model, steady state)		
Dimensions:	15.75" x 19" x 24" (Enhanced Performance)		
Weight:	40 kg (Enhanced Performance)		

Certified by:

Jim Liem, Operations Manager

07/27/201

Enviro Tec	hnology Service	es plc Air	Pollation Solations
Kingfisher Business Park, Lor Tel: + 44 (0) 1453 733200	ndon Road, Stroud, Glos, GL5 2E Fax: +44 (0)1453 733201	BY, UK Email: info@et.co.uk	www.et.co.uk
	ENGINEER'	S REPORT	

Tel: + 44 (0) 453 7	ENCIN	CEDIS DE	POPT			
		EER'S RE				
	Please consider the	environment befo	re printing this r	eport		
ET Ref No: 23498 Cust		r Order No:			EAZ1799600	
Engineer Name:	Lewis John		Visit 1	Гуре:	Setup & Test	
Enviro Client / Database	Name:		University	of Manche	ester	
Official Defra Site Name	(if applicable):			-		
Site Visit Start Date:	09/08/2018	Time:	11:00		GMT	
ite Visit End Date:	10/08/2018	Time:	15:15		(Data Elimination GMT	
Reported Fault / Task:	Service Control of the Control of th					
	EA-EP S/N: 3K60180500005016.					
dooted up OK. Software O Pressure stable at ~50:07 me: 32.01us. Laser A offs 126 scc/m, averaged over	OK, no warning alarms. Set timesta Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offse r 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O	
Booted up OK. Software OPressure stable at ~50:07 ime: 32.01us. Laser A offs 126 scc/m, averaged over	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O	
Booted up OK, Software OPressure stable at ~50:07 ime: 32.01us. Laser A offs 126 scc/m, averaged over measured leak rate: 0.04	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Parts Used:	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	
Pressure stable at ~50:07 time: 32.01us. Laser A offs (126 scc/m, averaged over	Torr. After 90 minutes temperatur set voltage: -2.377V. Laser B offser 10 measurements). Pump perfor Torr/minute). Overnight stability te	e was stable at ~ et voltage: -1.471 mance check OK	45C. Laser A rin V. Response to ((pumped down	g down tim gas OK (pe	e: 8.40us. Laser B ring down eaked within 10s). Flow rate O rr in 2 minutes). Leak check C	

Total Time:

01:04:15