TRIMS			Formate n Issue Date	o:Trims/RTM/R0											
			PREVENTIVE MAINTENANCE PLAN												
GT N	MCN	M/C NAME	C4-4			•									
SL.No.	M/C No		Status	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	JAN	FEB	MAR
1	TS/MC/01	LATHE MACHINE	P/A		P										
2	TS/MC/01	LATHE MACHINE	P/A		2022-05-24										
3	TS/MC/01	LATHE MACHINE	P/A		P										
4	TS/MC/01	LATHE MACHINE	P/A		P										
5	TS/MC/01	LATHE MACHINE	P/A		P										
6	TS/MC/01	LATHE MACHINE	P/A		2022-05-25										
7	TS/MC/01	LATHE MACHINE	P/A		P										
8	TS/MC/01	LATHE MACHINE	P/A		P										
9	TS/MC/01	LATHE MACHINE	P/A		2022-05-27										

r	·								
	TRIMS SOLUTIONS	FormatNo.TRIMS/MTN/RO							
TRIMS	TRIVIS SOLUTIONS	Issue Date:01.02.2019							
TKIIVIS	PREVENTIVE MAINTENANCE CHECKLIST	Rev.No.00							
	FREVENTIVE MAINTENANCE CHECKLIST		Rev Date:						
	Machine No: TS/MC/01								
	Date: 2022-03-09  Machine Name:L								
SL:NO	Check Points		Observation						
36	Grinding wheel checked		nice						
37	machine on/off checked		good						
38	shaft working		good						
39	machne working condition		good						
40	belt checked		good						
41	Grinding wheel checked		ZZ						
42	machine on/off checked		ZXZ						
43	shaft working		12121						
44	machne working condition		1231						
45	belt checked		123						

			TRIMS SOLUTIONS													Formate no:Trims/RTM/R0 Issue Date:12-12-12																		
TRIMS				DAILY MAINTENANCE CHECKLIST															Rev.No:00 Rev Date:1-1-22															
<b>A</b> achine	Name: LATHE N	MACHINE	Mac	hine	No:	TS/	MC/	01										Mo	nth ]	Nan	ne: J	anua	ary						Yea	r: 20	022			-
CLN	Check points		Frq																		Day	S												
Sl.No:	Спеск	rk points P		01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
15	Grinding wheel checked		D																											X				
17	machine on/off checked		D							X																								
18	shaft v	shaft working								X																								
20	belt cl	belt checked								X																								
85	Grinding wh	Grinding wheel checked									X																							
86	machine on/off checked		D								X																							
87	shaft v	working	D								X																						_	
88	machne work	king condition	D								X																							
89	Grinding wl	heel checked	D																								X							

					TD	IMS SOLUTIONS						Fo	ormatNo.TRI	MS/MTN/RO
TRI	MS					Issue Date:	01.02.2019							
IXI	VIS					Rev.No.00								
						Date:								
SL:NO	MACHINE CODE	MACHINE NAME	DATE	BREAKDOWN DETAILS	ROOT CAUSE	PREVENTIVE ACTION	END TIME	SPARES USED	SPARES COST	SPARES QTY	SPARES TOTAL COST	ATTEND BY	REMARKS	File Name
10	TS/MC/01	LATHE MACHINE	2022- 03-01	Grinder Belt Cut	Self Life Experied	Change belt in 2 month once	13:06	Belt	500	0	0	sekar	good	C:\fakepath\logo.jpg
11	TS/MC/01	LATHE MACHINE	2022- 03-02	Printer Shorted	Rain water sprayed in plugs	Don't keep near windows	16:10	Nozzle	2000	0	0	hema	bad	C:\fakepath\page1- 01.jpg
12	TS/MC/01	LATHE MACHINE	2022- 03-03	Motor Burned	Over loaded operation	Follow Specified Weight before operations	23:13	Nozzle	2000	5	10000	sri	good	break down3.png
13	TS/MC/01	LATHE MACHINE	2022- 05-18	Motor Burned	Over loaded operation	Follow Specified Weight before operations	23:15	Nozzle	2000	0	0	fdd	cfbdvf	C:\fakepath\page1- 01.jpg