Report No.: **R307210921-01** Date of Inspection: **21/09/2021**

Name and Address of the Owner		Place of Inspection	Technical referential
SUDHIR		**Riyadh- Bolivard Area**	**ANSI SIA A92.5**
Certificate No.: **C307210921.6149**		Manufacturer / Date of Manufacture **GENIE/2018**	
BV Job No: **ZIG:4569959**	Owner Id No: **G18SL-036**	Model No: **GS5390**	Manufacturer Serial No: **G590D-964**

Reference	Nb.	Item	Status	Comments
Historical Data				
A-92.6-6.3	1	Equipment Manuals	pass	
A-92.6-6.15.1(2)	2	Annual Inspection Records	pass	
A-92.6-6.15.1(3)	3	Maintenance records	pass	
A-92.6-6.17	4	Manufacture's Safety Bulletins	pass	
Safety Devices				
A-92.6-6.14	6	Visual /Audio Safety Devices	pass	
O-1926.453(b)(2)(ix)	7	Upper control override	pass	
A-92.6-4.6.4	8	Emergency Hand Pump	pass	
A-92.6-4.6.3	9	Emergency Stops	pass	
O-1926.15-(a)	10	Fire Extinguishers	pass	
A-92.6-4.6.1(3)	11	Platform Foot/dead Man Switch	pass	
A-92.6-4.8.2	12	Pothole Protectors	pass	
O-1926.502(d)(15)	13	Fall protection Anchorage Point	pass	
	14	Other		
Outriggers / Stabilizers				
A-92.6-6.6(1)	15	Controls	pass	
A-92.6-6.6(5)	16	Hydraulic Cylinders / hoses/Fittings	pass	
A-92.6-6.6(6)	17	Pins/Keepers	pass	
A-92.6-6.6(6)	18	Beams/Boxes	pass	
A-92.6-6.6(7)	19	Warning Decals	pass	
A-92.6-6.6(8)	20	Floats/Pads	pass	
A-92.6-4.8.2	21	Holding Valves	pass	
	22	Other		
Carrier				
A-92.6-4.13	23	Instructions and Markings	pass	
A-92.6-7.10	24	Hazardous (Classification) Location	pass	
A-92.6-4.17	25	Weather-Resistant Box for Manuals	pass	
A-92.6-6.6(1)	26	Lower Controls Operation	pass	
A-92.6-4.6.2(5)	27	Lower Controls Markings	pass	
A-92.6-6.6(5)	28	Hydraulic Tubes/Hoses/Fittings	pass	
A-92.6-6.6(5)	29	Hydraulic Filters/levels/Leaks	pass	
A-92.6-4.15.1	30	Fuel/Exhaust Systems	pass	

THIS IS TO CERTIFY THAT the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per technical ref mentioned above. The liabilities are as per Bureau Veritas General Conditions of Services.

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null and v Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or of judgment, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating t limitation, patents, workmanship, materials, safety, performance in operation and/or reliability

Reference	Nb.	Item	Status	Comments
Carrier(Continued)				
A-92.6-6.6(1)	31	Steering Linkage Components	pass	
A-92.6-6.6(6)	32	Suspension/Axle Mounting	pass	
A-92.6-6.6(1)	33	Transmission/Drive Train	pass	
A-92.6-6.6(1)	34	Braking System	pass	
A-92.6-6.6(4)	35	Passive Brake	pass	
A-92.6-4.18	36	Electrical Harness & Routing	pass	
A-92.6-4.15.2	37	Battery Charging	pass	
A-92.6-4.15.2	38	Batteries Leaks /Fluid Level(s)	pass	
A-92.6-7.3.3(7)	39	Wheels/Tires/PSI	pass	
Scissors Assembly				
A-92.6-6.6(5)	42	Hydraulic Cylinder(s)	pass	
A-92.6-6.6(5)	43	Hydraulic Hoses/Fittings	pass	
A-92.6-7.3.3(4)	44	Hydraulic Leaks	pass	
A-92.6-6.6(6)	45	Base/Pivot Pins	pass	
A-92.6-6.6(7)	46	Warning Decals	pass	
A-92.6-6.6(4)	47	Maintenance/Safety Lock	pass	
A-92.6-6.6(6)	48	Beam Welds/Deformation	pass	
	49	Other		
Work Platform				
A-92.6-4.12.4	50	Access Gate/Chain	pass	
A-92.6-4.12.2.1	51	Guardrail System: Top Rail	pass	
A-92.6-4.12.2.2	52	Guardrail System: Mid Rail	pass	
A-92.6-4.12.3	53	Toe Boards	pass	
A-92.6-4.12.1	54	Slip Resistant Surface	pass	
O-1926.500(f)(3)(ii)	55	Falling Object Protective Screen	pass	
A-92.6-6.6(1)	56	Upper Controls Operation	pass	
A-92.6-4.6.1(6)	57	Upper Controls Marking	pass	
A-92.6-6.6(7)	58	Instruments/Gauges	pass	
A-92.6-7.3.3(5)	59	Cables/Wiring Harness	pass	
O-1926.500(c)(2)	60	Platform Extension	pass	
A-92.6-6.6	61	No-Load Operational Test	pass	

Authorized name: Ahmed Mahmoud Signature Issued at Riyadh office on 26th "Sep. 2021	B&F Riyadh Team Leader name: Eng. ELIE KARAM Signature

THIS IS TO CERTIFY THAT the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per technical ref
mentioned above. The liabilities are as per Bureau Veritas General Conditions of Services.
The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null and v
Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.
Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or
of judgment, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.
This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating t
limitation, patents, workmanship, materials, safety, performance in operation and/or reliability