C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH
INSPECTION & TRAINING
Values For Quality

هيكلة
الفحص والتدريب
قيم الجودة

س.ت. : ٤٠٣٠٣٥٣٢٠٣
غرفة تجاره : ٣٢٤٤٦٨
هاتف : ٩٦٦ ١٢ ٦٥٥ ١٨٨٨+
فاكس : ٩٦٦ ١٢ ٢٨٧ ٧٧٧٠+
ISO 9001:2015

THIRD PARTY INSPECTION CERTIFICATE

MANLIFT

Certificate No : HIT-CRT-22-1175 Job No JO-INS-22-606

Sticker No	1190
Result	Pass

Timesheet	CL-1148
Checklist	CL-1148

Client Name & Address		Inspection Date	24-Mar-2022
Sudhir Equipment Rental Company		Expiration Date	23-Sep-2023
Yanbu		Validity	6 Month's
Kingdom of Saudi Arabia		**Types of Inspection**	
Equipment Location	Yanbu	Periodic Visual & Functional	

Equipment Description	Load Test Chart			
Manlift crane with single basket,	**Boom ↔**	**Radius →**	**Test Load**	**S.W.L.**
Double operative control system,	**(Meter)**	**(Meter)**	**(Tonne)**	**(Tonne)**
High performance to power ratio,	NA	NA	NA	NA
Diesel driven hydraulic.				

Load Limit (S.W.L.)	230 kg	Manufacturer	JLG
Serial No.	0300236632	Date of Mfg.	NA
Model	800 AJ	Owner ID/Plat No	S26AJ-048
Horizontal Outreach	15.8 m	Max Platform Height	24.38 m
Machine Height	3.0 m	Machine Weight	15,757 kg
Wire Rope Dia	**Main: NA Aux: NA**	Engine Power	61 kW
Boom Length	NA	Angle of Span	NA
Wheel Type	Tyre	Person Allowed	2

Previous Inspection Details	**Next Inspection Date**	Reference Standard
NA	24-Sep-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By: ISRAN SHAREEF

HAYKALAH 001

Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA

EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com

٦٩٨٨ ابو العباس ابن عبدالمطالب
اشاتيى دستريك، جدة ٢٣٥١٣-٢٩٧٠
المملكة العربية السعودية