REPORT OF VISUAL EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Client Name & Address:	SUDHIR EQUIPMENT RENTAL COMPANY.		
Work Order No.	ZAM-5690-03-24	**Report No.**	ZAMIL-R22922 / VIS
Place Of Inspection	DAMMAM 2ND INDUSTRIAL AREA	**Report Date**	
Date of Last Inspection	N/A	**Date of Inspection**	30/03/2024
Customer Requisition No.	N/A	**Date of Next Inspection**	29/09/2024
Applicable Standards	ANSI A92.6	**Issued Sticker No.**	ZAM-W-18164
O.E.M / C.O.C No. / Drawings	1900-01-01	**Color Code (If Applicable)**	N/A
Equipment Used	N/A	**Model No.**	800AJ

Equipment Serial No.	Equipment I.D	QTY	Description	Capacity/SWL (Ton)
0300236629	S26AJ-059	01	MANLIFT -Manufacturer : JLG -AWP Type : Articulated -Engin :Diesel -AWP Height : 26 Meter -Service Hours : 500 Articulated Boom Z80 / 60 / 800AJ Note : Visual inspection and functional test has been performed on the above mentioned equipment, during the time of inspection no any abnormality found.	227 KG

Is this the first examination after installation or assembly at a new site or location:	☐ YES ☑ NO
If the answer to the above question is YES. Has the equipment been installed correctly?	☐ YES ☐ NO ☑ NA
Was the thorough examination carried out Within an interval of 3 months?	☐ YES ☑ NO
Was the thorough examination carried out Within an interval of 6 months?	☑ YES ☐ NO
Was the thorough examination carried out Within an interval of 12 months?	☐ YES ☑ NO
In accordance with an examination scheme?	☑ YES ☐ NO
After the occurrence of exceptional circumstances?	☐ Yes ☑ No
Identification of any part found to have a defect which is or could become a danger to person and a description of the defect (if none state none): NONE	
Is the above a defect which is of immediate danger to persons	☐ YES ☑ NO
Is the above a defect which is not yet but could become a danger to persons? (If yes state the day by when)	☐ YES ☑ NO Date:
Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**	
Particulars of any tests carried out as part of the examination: (If none state NONE): **NONE**	
Inspection Result:	**During the time of Inspection Result found satisfactory - Is this Equipment Safe to Operate?** ☑ YES ☐ NO

This certificate by company under its general conditions of services. This issuance of this certificate does not exonerate the buyers or sellers from exercising all their rights discharging all their liabilities under the contacts of sale. Stipulations to contrary are not binding on the company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the free or commission. The above findings are limited to date place of intervention only. The company is neither an insurer not a guarantor disclaims all liabilities in such capabilities.

Inspected By Qualified: LEEA & ASNT NDT Level II		Reviewed By		Stamp
Name:	Abdullah Ali	**Name:**	Mohamed Atwa	
Position:	Inspector	**Position:**	Technical supervisor	
Signature:	This is Draft Certificate	**Signature:**	This is Draft Certificate	

Name and address of employer of persons making and authenticating this report: Zamil Inspection & Contracting Co, King Fahad Road–Al-Dhabab Avenue–Dammam 32261
C.R.: 2050069798–Email: operations@zamil.sa

Zamil Inspection & Contracting Co.

+966555052687 info@zamil.sa

NO. ZAM-W-18164

Equipment Type	:	MANLIFT
capacity/SWL	:	227 KG
Equipment ID	:	S26AJ-059
Equipment S.N.	:	0300236629
Inspection Date	:	30/03/2024
Next Insp Date	:	29/09/2024
Inspected By	:	Abdullah Ali