INI.C.01

# CERTIFICATE

## Of Test and Thorough Examination of Crane or Other Lifting Appliance

Certificate No.: **C307211007-6157**

Date of Inspection: **07th Oct. 2021**

| Name and Address of the Owner | | Place of Inspection | Technical referential |
|---|---|---|---|
| **SUDHIR** | | **Riyadh – Metro Project** | **ANSI SIA A92.5** |
| | | Manufacturer / Date of Manufacture | |
| | | **GENIE/2018** | |
| BV Job No: | Owner Id No: | Model No: | Manufacturer Serial No: |
| **Zig: 4569959** | **G18SL-064** | **GS5390** | **GS90D-600** |

**Equipment Description**

Type of equipment : **Scissor Lift**

Capacity: **680 Kg** - MAX. Platform Height: **17.9 Meter** - Operation weight: **7515 Kg**

| Description of Test | Test Load (Kg) | SWL (Kg) |
|---|---|---|
| **Based on Thorough Visual Examination, Functional Test**<br><br>**Load test**<br>**Load test with 110%**<br><br>**New Sticker No.:LFT-S.03-6157** | **750** | **680** |

**Based on Thorough Visual Examination, Functional Test and Proof Load test the equipment described above was found satisfactory at the time of Inspection.**

| Date of Last Examination | Last date for dismantle | Date of Last Proof Load Test | Date of Next Proof Load Test (if applicable) |
|---|---|---|---|
| **N/A** | **06/04/2022** | **N/A** | **After any Major repair or Modification** |

| | |
|---|---|
| Authorized name: Ahmed Mahmoud<br>Signature:<br><br>Issued at Riyadh office on 10th Oct. 2021 | B and F Riyadh Team Leader name: Eng. ELIE KARAM<br>Signature |

**THIS IS TO CERTIFY THAT** the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per technical referential mentioned above. The liabilities are as per Bureau Veritas General Conditions of Services.

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null and void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.
Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgment, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.
This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation, patents, workmanship, materials, safety, performance in operation and/or reliability

Report No.: **R307211007-03**

Date of Inspection: **07/10/2021**

| Name and Address of the Owner | | Place of Inspection | Technical referential |
|---|---|---|---|
| **SUDHIR** | | **Riyadh- Metro Project** | **ANSI SIA A92.5** |
| Certificate No.: **C307211007.6157** | | Manufacturer / Date of Manufacture **GENIE/2018** | |
| BV Job No: **ZIG:4569959** | Owner Id No: **G18SL-064** | Model No: **GS5390** | Manufacturer Serial No: **GS90D-600** |

| Reference | Nb. | Item | Status | Comments |
|---|---|---|---|---|
| **Historical Data** | | | | |
| A-92.6-6.3 | 1 | Equipment Manuals | pass | |
| A-92.6-6.15.1(2) | 2 | Annual Inspection Records | pass | |
| A-92.6-6.15.1(3) | 3 | Maintenance records | pass | |
| A-92.6-6.17 | 4 | Manufacture's Safety Bulletins | pass | |
| **Safety Devices** | | | | |
| A-92.6-6.14 | 6 | Visual /Audio Safety Devices | pass | |
| O-1926.453(b)(2)(ix) | 7 | Upper control override | pass | |
| A-92.6-4.6.4 | 8 | Emergency Hand Pump | pass | |
| A-92.6-4.6.3 | 9 | Emergency Stops | pass | |
| O-1926.15-(a) | 10 | Fire Extinguishers | pass | |
| A-92.6-4.6.1(3) | 11 | Platform Foot/dead Man Switch | pass | |
| A-92.6-4.8.2 | 12 | Pothole Protectors | pass | |
| O-1926.502(d)(15) | 13 | Fall protection Anchorage Point | pass | |
| | 14 | Other | | |
| **Outriggers / Stabilizers** | | | | |
| A-92.6-6.6(1) | 15 | Controls | pass | |
| A-92.6-6.6(5) | 16 | Hydraulic Cylinders / hoses/Fittings | pass | |
| A-92.6-6.6(6) | 17 | Pins/Keepers | pass | |
| A-92.6-6.6(6) | 18 | Beams/Boxes | pass | |
| A-92.6-6.6(7) | 19 | Warning Decals | pass | |
| A-92.6-6.6(8) | 20 | Floats/Pads | pass | |
| A-92.6-4.8.2 | 21 | Holding Valves | pass | |
| | 22 | Other | | |
| **Carrier** | | | | |
| A-92.6-4.13 | 23 | Instructions and Markings | pass | |
| A-92.6-7.10 | 24 | Hazardous (Classification) Location | pass | |
| A-92.6-4.17 | 25 | Weather-Resistant Box for Manuals | pass | |
| A-92.6-6.6(1) | 26 | Lower Controls Operation | pass | |
| A-92.6-4.6.2(5) | 27 | Lower Controls Markings | pass | |
| A-92.6-6.6(5) | 28 | Hydraulic Tubes/Hoses/Fittings | pass | |
| A-92.6-6.6(5) | 29 | Hydraulic Filters/levels/Leaks | pass | |
| A-92.6-4.15.1 | 30 | Fuel/Exhaust Systems | pass | |

**THIS IS TO CERTIFY THAT** the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per technical ref mentioned above. The liabilities are as per Bureau Veritas General Conditions of Services.

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null and v Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, o of judgment, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating limitation, patents, workmanship, materials, safety, performance in operation and/or reliability

| Reference | Nb. | Item | Status | Comments |
|---|---|---|---|---|
| **Carrier(Continued)** | | | | |
| A-92.6-6.6(1) | 31 | Steering Linkage Components | pass | |
| A-92.6-6.6(6) | 32 | Suspension/Axle Mounting | pass | |
| A-92.6-6.6(1) | 33 | Transmission/Drive Train | pass | |
| A-92.6-6.6(1) | 34 | Braking System | pass | |
| A-92.6-6.6(4) | 35 | Passive Brake | pass | |
| A-92.6-4.18 | 36 | Electrical Harness & Routing | pass | |
| A-92.6-4.15.2 | 37 | Battery Charging | pass | |
| A-92.6-4.15.2 | 38 | Batteries Leaks /Fluid Level(s) | pass | |
| A-92.6-7.3.3(7) | 39 | Wheels/Tires/PSI | pass | |
| **Scissors Assembly** | | | | |
| A-92.6-6.6(5) | 42 | Hydraulic Cylinder(s) | pass | |
| A-92.6-6.6(5) | 43 | Hydraulic Hoses/Fittings | pass | |
| A-92.6-7.3.3(4) | 44 | Hydraulic Leaks | pass | |
| A-92.6-6.6(6) | 45 | Base/Pivot Pins | pass | |
| A-92.6-6.6(7) | 46 | Warning Decals | pass | |
| A-92.6-6.6(4) | 47 | Maintenance/Safety Lock | pass | |
| A-92.6-6.6(6) | 48 | Beam Welds/Deformation | pass | |
| | 49 | Other | | |
| **Work Platform** | | | | |
| A-92.6-4.12.4 | 50 | Access Gate/Chain | pass | |
| A-92.6-4.12.2.1 | 51 | Guardrail System: Top Rail | pass | |
| A-92.6-4.12.2.2 | 52 | Guardrail System: Mid Rail | pass | |
| A-92.6-4.12.3 | 53 | Toe Boards | pass | |
| A-92.6-4.12.1 | 54 | Slip Resistant Surface | pass | |
| O-1926.500(f)(3)(ii) | 55 | Falling Object Protective Screen | pass | |
| A-92.6-6.6(1) | 56 | Upper Controls Operation | pass | |
| A-92.6-4.6.1(6) | 57 | Upper Controls Marking | pass | |
| A-92.6-6.6(7) | 58 | Instruments/Gauges | pass | |
| A-92.6-7.3.3(5) | 59 | Cables/Wiring Harness | pass | |
| O-1926.500(c )(2) | 60 | Platform Extension | pass | |
| A-92.6-6.6 | 61 | No-Load Operational Test | pass | |

| | |
|---|---|
| Authorized name: Ahmed Mahmoud<br>Signature<br><br>BUREAU VERITAS SAUDI ARABIA<br><br>Issued at Riyadh office on 10th Oct. 2021 | B&F Riyadh Team Leader name: Eng. ELIE KARAM<br>Signature |

**THIS IS TO CERTIFY THAT** the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per technical ref mentioned above. The liabilities are as per Bureau Veritas General Conditions of Services.

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null and v Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, o of judgment, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating limitation, patents, workmanship, materials, safety, performance in operation and/or reliability