ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF LOAD TEST THOROUGH EXAMINATION OF MOBILE ELEVATING WORK PLATFORM

Date of thorough examination : 15-01-2026	Date of issue : 15-01-2026	Report No. : ESICO-LFT-R25-6316

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY	RIYADH	7968	SASO GSO EN 280,ANSI A92.5

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SG125L-066 OR GS90D-684	SCISSOR LIFT MODEL:GS3384 MAX.PLATFORM HEIGHT:10.1M MAX.WORKING HEIGHT:12.06M MAX.WIND SPEED:12.5M/S SIDE FORCE:400N SIZE(LxW):3.94x2.34M	RATED LOAD:1134KG(4PERSON+TOOLS)	UNKNOWN	GENIE

Is this the first examination after installaton or assembly at a new site or location?	Yes	-	No	✗	Was the examination carried out within an interval of?	-	6 Months
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-	In accordance with an examination scheme?	Yes ✓	No -
					After the occurence of exceptional circumstances?	Yes -	No ✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST.	
Observation/additional comments relative to this thorough examination : AT THE TIME OF INSPECTION MENTION ABOVE NAME OF EQUIPMENT IS SAFE TO OPERATE.DO NOT OVERLOAD.	

QA/QC DEPARTMENT

For confirmation scan QR code
search with report number : ESICO-LFT-R25-6316

✓ Safe to operate

Next Inspection : 14-07-2026

Inspected by : Jay Prakash

INSPECTOR

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM نيوم 1100004098 | شركة المياه الوطنية National Water Company 33564 | 10739 | سابك sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS ACCREDITED