C.R.NO. : 4030353203
C.C.J.NO. : 324468
TEL : +966 12 655 1888
FAX : +966 12 287 7770
ISO 9001:2015

HAYKALAH
INSPECTION & TRAINING
Values For Quality

هيكلة
الفحص والتدريب
قيم الجودة

س.ت. : ٤٠٣٠٣٥٣٢٠٣
غرفة تجارة : ٣٢٤٤٦٨
هاتف : ٦٥٥ ١٨٨٨ ١٢ ٩٦٦+
فاكس : ٢٨٧ ٧٧٧٠ ١٢ ٩٦٦+
ISO 9001:2015

THIRD PARTY INSPECTION CERTIFICATE
MANLIFT

Certificate No : HIT-CRT-23-2169

Job No JO-INS-23-1170

Sticker No	1814
Result	Pass

Timesheet	CL-4009
Checklist	CL-4009

Client Name & Address		Inspection Date	3-Jan-2023
Sudhir Equipment Rental Company		Expiration Date	2-Jul-2023
Jeddah		Validity	12 Month's
Kingdom of Saudi Arabia		**Types of Inspection**	
Equipment Location	Asfan	Periodic Visual & Functional	

Equipment Description	Load Test Chart			
Manlift crane with single basket,	**Boom ↔**	**Radius →**	**Test Load**	**S.W.L.**
Double operative control system,	**(Meter)**	**(Meter)**	**(Tonne)**	**(Tonne)**
High performance to power ratio,	NA	NA	NA	NA
Diesel driven hydraulic.				

Load Limit (S.W.L.)	230 kg
Serial No.	0300239873
Model	860SJ
Max.Horiz Outreach	22.86 m
Machine Height	3.05 m
Wire Rope Dia	**Main: NA** **Aux: NA**
Boom Length	NA
Wheel Type	Tyre

Manufacturer	JLG
Date of Mfg.	2018
Owner ID/Plate No	S28SJ-081
Max Platform Height	26.21 m
Machine Weight	16,732 kg
No. of Reeve	NA
Angle of Span	NA
Person Allowed	2

Previous Inspection Details	Next Inspection Date	Reference Standard
NA	03-Jul-23	ASME A 90.1

Recommendation

Found satisfactory at the time of Inspection.

Authorized By: ASHADULLAH KHAN

Inspected By: KALEEM SHARIEF

Signature & Stamp

No liabilities will be considered against Haykalah Inspection Est. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance. The concerned inspector or representative has thoroughly examined the equipment in accordance to the relevant standards. Inspection indicates that the mentioned equipment/tools/machine has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use with provided their regular maintenance and operated by a certified operator. This certificate/report shall not be generated without an official approval in between Haykalah Inspection Est. and Client. Certificate becomes invalid if any modification/repair is made to the equipment.

6988 ABU AL ABBAS IBN ABDULMUTALIB
ASH SHAHTI DISTRICT, JEDDAH 23513-2970
KINGDOM OF SAUDI ARABIA

EMAIL: hit@hakalah.com
WEB: www.haykalah-hit.com

٦٩٨٨ ابو العباس ابن عبدالمطالب
اشاتي دستريك، جدة ٢٣٥١٣-٢٩٧٠
المملكة العربية السعودية