BUREAU VERITAS

BV No. 0101026

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: MAY 26, 2021	Inspection Time: —	Previous Sticker No. 9463 Issued By Zamil
Department / Contractor: SUDHIR	Equipment Number: S22S6-085	Equipment Location: DMM [illegible]	Inspection Result: ☐ Pass ☐ Fail	New Sticker No.: BV-21-0689
Manufacturer: GENIE	Model: S65	Capacity: 227KG / Type: MANLIFT	Equipment Serial Number: S60D-1390	Sticker Expiration Date: NOV 25, 2021

Above Equipment was inspected by bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective action are listed below . Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Permit to inspection and function test for	
	Boom supported elevating work platform	
	As per ASME B30.7 and ANSI 92.5	
	Pass	

RECEIVER NAME: Mahtab Khan SIGNATURE: MK INSPECTOR NAME: M. [illegible]

BADGE#: 2470523982 TELEPHONE No.: 0581849646 TELEPHONE No.: [illegible]

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy - 2nd Copy - Inspector Agency