BUREAU VERITAS

BV No. 0104489

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date FEB 16, 2022	Inspection Time —	Previous Sticker No. 21-2410 Issued By BV
Department / Contractor SUOHSR	Equipment Number S225G-086	Equipment Location DAMMAM	Equipment Result ☑ Pass ☐ Fail	New Sticker No. BV-21-3251
Manufacturer GENIE	Model S65	Capacity 227KG / Type MGWP	Equipment Serial Number S60D-1391	Sticker Expiration Date AUG 15, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for	
	Boom supported elevating work platform	
	as per as Saudi Aramco GI 7.036 and 92.5	
	"PASS"	

RECEIVER NAME: UBAYA ALLA SIGNATURE: Ubaya INSPECTOR NAME: M. Omar

BADGE#: TELEPHONE No.: TELEPHONE No.: 18 [illegible]

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency