BUREAU VERITAS

BV No. 0107362

LIFTING EQUIPMENT INSPECTION REPORT	Area: HAWTYAH	Inspection Date: DEC 06,2022	Inspection Time: 9:00	Previous Sticker No. 21-5041 Issued By BV
Department / Contractor: SUDHIR	Equipment Number: S16AG-103	Equipment Location: HUGRS	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-6975
Manufacturer: GENIE	Model: ZX5 125RT	Capacity: 227KG / Type: MEWP	Equipment Serial Number: ZX5 25D-1975	Sticker Expiration Date: JUNE 05, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for	
	Boom supported elevating work platform	
	As per Aramco GI 7.030, para 5.2.5	
	"PASS"	

RECEIVER NAME: THAJSEER SIGNATURE: INSPECTOR NAME: M. OMARS

BADGE#: 8037 TELEPHONE No.: 0552228031 TELEPHONE No.: 18-009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency