BUREAU VERITAS

BV No. 09409

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: MARCH 28, 2021	Inspection Time: —	Previous Sticker No.: 20-07950 Issued By: [illegible]
Department / Contractor: SUDHIR	Equipment Number: S16A6-104	Equipment Location: DAMMAM	Inspection Result: [x] Pass [ ] Fail	New Sticker No.: 21-11462
Manufacturer: GENIE	Model: Z45 25RT	Capacity: 227KG	Type: MANLIFT	Equipment Serial Number: Z45250-1958	Sticker Expiration Date: SEP 27, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and Function test for	
	Boom supported Elevating work platform	
	As per as SAROMCO GI 7.030, ANSI 92.5.	
	'PASS'	

RECEIVER NAME: Maktab Khan SIGNATUE: [illegible] INSPECTOR NAME: [illegible]

BADGE#: 2470.52 2982 TELEPHONE No.: 0558184646 TELEPHONE No.: [illegible]

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency