BUREAU VERITAS

BV No. 0104466

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUBAIL	Inspection Date: FEB 06, 2022	Inspection Time: —	Previous Sticker No. 21-1559 Issued By BV.
Department / Contractor: SVOLTSR	Equipment Number: S285G-107	Equipment Location: NABA PROJECT	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-3227
Manufacturer: GENIE	Model: S85	Capacity: 227KG / Type: MEWP	Equipment Serial Number: S85D-807	Sticker Expiration Date: AUG 05, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and Function test for	
	Boom Supported Elevating work Plat form.	
	As per ASARAMCO GI 7.03, ANSI 92.5	
	"PASS"	

RECEIVER NAME: UBAYDALLA SIGNATURE: INSPECTOR NAME: M. Omar

BADGE#: TELEPHONE No.: TELEPHONE No.:

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency