Applus VELOSI

Velosi Saudi Arabia Co. Ltd.

P.O. BOX 7031 - Dhahran 34247 - Tel: +966 13 839 4292 - Fax : +966 13 839 3671

WO.08.21.0585

JOB ORDER

No. : 20219

LIFTING EQUIPMENT / NON LIFTING (HEAVY EQUIPMENT) INSPECTION REPORT		Location: SHUQAIQ POWER	Inspection Date : 30 AUG 2021
Department / Contractor : SUDAIR BENTAL		Body No./ID No. S285G-109	Equipment SN.: S850-804
Manufacturer: GENIE-2018		Model: S85	Capacity: 227 Kg / Type : MANLIFT
Previous Report / Sticker No.: 73963	Issued by: VELOSI	New Sticker No. 77023	Next Inspection Date: 29 FEB 2022

No.	GENERAL PARTS	RESULTS PASS	RESULTS FAIL	PRIMERY MOVERS	RESULTS PASS	RESULTS FAIL
1	ENGINE	✓		TRACK PADS (CRAWLER TYPE)		
2	WHEELS / TIRES	✓		OUT RIGGERS (CHECK OF LEAKS)		
3	CAB/SEATS/SEAT BELTS			OUT RIGGER PADS		
4	AIR-CON SYSTEM			HYDRAULIC SYSTEM	✓	
5	GAUGES	✓		WINCH/HOIST/WIRE ROPE		
6	BRAKES/ PEDAL LEVER	✓		HOOK BLOCK ANCHOR		
7	STEERING WHEEL	✓		PANELS/BOOM/JIB	✓	
8	HYDRAULIC SYSTEM	✓		WIRE ROPE DRUM		
9	ELECRICAL SYSTEM	✓		COUNTER WEIGHT		
10	LIGHT (SIGNAL & BACON) HORNS, WIPER,ETC.	✓		ATTACHMENTS (FORKS/BUCKETS/ETC) MENTION		
11	WIND SHEILD, MIRRORS			PUDITONY	✓	
12	CONTROL LEVER	✓				
13						

No.	SAFTY	RESULTS PASS	RESULTS FAIL	OTHERS	RESULTS PASS	RESULTS FAIL
1	LIMT/CUT - OFF SWITCHES	✓				
2	LOCK PINS (EXTENDED & RETRACTED)	✓				
3	COMPUTER (SLI & IMI)					
4	OVERLOAD WARINIG					
5	TILTING BUZZER	✓				
6	CONTROL LEVERS	✓				
7	AXLES / OUT RIGGERS	✓				
8	HOOK BLOCK / SAFTY LATCH/ SHEAVES					
9	ROTATING / BACK-UP WARNING ALARM LIGHT	✓				
10	SPARK ARRESTOR					
11	FIRE EXTINGUISHER	✓				

No.	EQUIPMENT ON OPERATION	RESULTS PASS	RESULTS FAIL
1	CHECK UNDER CHASIS FOR LEAKS AND OTHER MOVABLE PARTS IF THEY ARE GREASE CORRECTLY	✓	
2	CHECK WATER, OIL LEVELS/HYRADRAULICS AND TRANSMISSION	✓	
3	BOOM OPERATION RISING AND A FRAME (LOOK AT EVERY SECTION FOR STRESS CRACKS AND IF ALL STEEL ARE GREASED ALL)	✓	
4	CHECK HOOK BLOCK, SHEAVS FOR DAMEGE, SAFTY LATCHES CHECK ALL ANCHORS AND MOVEMENT OF HOOK BLOCK		
5	INSPECT HOIST ROPE FOR ANY KINKS/SPLAYING, IF NEED LUBING IT RUNS THE CORRECT PATH, FEEDS ON TO THE HOIST AND SPOOL CORRECTLY		
6	CHECK HOLDING VALVES AND CYLINDER SEALS ON BEAMS AND JACK FOR ANY LEAKS	✓	
7	OTHERS		

REMARKS : SATISFACTION

THIS TIME SHEET WILL SERVE AS TEMPORARY CIRTIFCATE FOR 7 SEVEN DAYS AFTER THE DATE OF ISPECTION

Reciever Name : ADNAN Signature : Adnan Inspector Name / Stamp : MOHAMMAD IQBAL

Badge No. Mobile No. 0581664440 Signature :

DISTRIBUTION : 1ST PAGE - CLIENT COPY 2ND PAGE ACCOUNTING DEPT. 3RD PAGE - INPECTOR FILE