BUREAU VERITAS

BV No. 09422

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: APRIL 04, 2021	Inspection Time:	Previous Sticker: No. 11162 Issued By: Zamil
Department / Contractor: SUDAIR	Equipment Number: S16AG-119	Equipment Location: DMMAM	Inspection Result: [✓] Pass [ ] Fail	New Sticker No.: BV-21-005
Manufacturer: GENIE	Model: Z45/25RT	Capacity: 227KG	Type: MANLIFT	Equipment Serial Number: Z45250-1974
				Sticker Expiration Date: OCT 03, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and functional test for	
	Boom supported Elevating work platform	
	As per ARAMCO 6570 301 and 5 yr. 5	
	"Pass"	

RECEIVER NAME: Mahtab Khan SIGNATUE: A. Khan INSPECTOR NAME: Jiaoing

BADGE#: 2470-523982 TELEPHONE No.: 0558496946 TELEPHONE No.: M. Alnard

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency