ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF LOAD TEST THOROUGH EXAMINATION OF MOBILE ELEVATING WORK PLATFORM

Date of thorough examination : 21-12-2025	Date of issue : 21-12-2025	Report No. : ESICO-LFT-R25-7059

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY	NESMA PROJECT RIYADH	8711	SASO GSO EN 280 & ANSI A92.6

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
S012ESL-1206 OR JPAC024C02265	SCISSOR LIFT MODEL:JCPT1212AC POWER:3.5KW VOLTAGE:24V INDOOR CAPACITY:2PERSION+157.85KG OUTDOOR CAPACITY:1PERSION+237.68KG MAX.PLATFORM HEIGHT:10.0M	TOTAL CAPACITY:317.51KG	2024	DINGLI MACHINERY

Is this the first examination after installaton or assembly at a new site or location?	Yes	-	No	✗
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-

Was the examination carried out within an interval of?	- 6 Months			
In accordance with an examination scheme?	Yes	✓	No	-
After the occurence of exceptional circumstances?	Yes	-	No	✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST.	
Observation/additional comments relative to this thorough examination : AT THE TIME OF INSPECTION THE EQUIPMENT ABOVE NAME IS SAFE TO OPERATE.	

For confirmation scan QR code
search with report number : ESICO-LFT-R25-7059

✓ Safe to operate

Next Inspection : 20-06-2026

Inspected by : Jay Prakash

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM نيوم 1100004098 | شركة المياه الوطنية National Water Company 33564 | 10739 | سابك sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS ACCREDITED