شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

# CERTIFICATE OF LOAD TEST THOROUGH EXAMINATION OF MOBILE ELEVATING WORK PLATFORM

| | | |
|---|---|---|
| Date of thorough examination : **08-12-2025** | Date of issue : **08-12-2025** | Report No. : **ESICO-LFT-R25-6280** |

| Name & Address of employer | Location | Sticker | Standards |
|---|---|---|---|
| **SUDHIR EQUIPMENT RENTALS COMAPNY** | **Riyadh** | **7932** | **SASO ISO EN 280** |

| Equipment Identification No | Equipment Description | Safe Working Load(s) | Date of Manufacture | Manufacturer Name |
|---|---|---|---|---|
| **SD12ESL-1210 OR JPAC024C02267** | **SCISSOR LIFT<br>MODEL:JCPT1212AC<br>Voltage: 24V Power: 3.5kW<br>Max. platform height:32.8 ft<br>Max.number of occupatans: 2<br>Max.wind speed: 28/mph** | **RATED LOAD: 317KG** | **DINGLI** | **2024** |

| | | | | |
|---|---|---|---|---|
| Is this the first examination after installaton or assembly at a new site or location? | Yes | - | No | ✗ |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes | - | No | - |

| | | | | |
|---|---|---|---|---|
| Was the examination carried out within an interval of? | - 6 Months | | | |
| In accordance with an examination scheme? | Yes | ✓ | No | - |
| After the occurence of exceptional circumstances? | Yes | - | No | ✗ |

| | |
|---|---|
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE | |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect? | N/A |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) | Yes by : N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A | |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE | |
| **Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory** | |

For confirmation scan QR code
search with report number : **ESICO-LFT-R25-6280**

QA/QC DEPARTMENT
EMAAR SUPPORT INSPECTION CO.

✓ Safe to operate

Next Inspection : 07-06-2026

Inspected by : Mohamed Askar Ali

INSPECTOR
C.R.: 2054100036

LEEA Full Member | أرامكو السعودية saudi aramco 10056897 | EP-Q4634 | NEOM نيوم 1100004098 | شركة المياه الوطنية National Water Company 33564 | 10739 | سابك sabic 001052261 | الشركة السعودية للكهرباء Saudi Electricity Company 05022531 | IAF | IAS ACCREDITED