BUREAU VERITAS

BV No. 07396

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUBAIL	Inspection Date: JAN 21, 2021	Inspection Time: —	Previous Sticker: No. 10148 Issued By Zamil
Department / Contractor: SUDAIR	Equipment Number: SAO SG-125	Equipment Location: J. sabic Gas Plant	Inspection Result: ☑ Pass ☐ Fail	New Sticker No.: 20-10974
Manufacturer: GENIE	Model: SX-125 XC	Capacity: 300KG / Type: Manlift	Equipment Serial Number: SX125D-168	Sticker Expiration Date: JULY 20, 2021

Above Equipment Was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's ASME and API standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for	
	Boom supported elevating work platform.	
	As per AS S.Aramco GI 7.030, ANSI, 92.5.	
	'Pass'	

RECEIVER NAME: Mahtab Khan SIGNATUE: A.Khan INSPECTOR NAME: 18-0069 Monsab

BADGE#: 2470523982 TELEPHONE No.: 0558149646 TELEPHONE No.:

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy -2nd Copy - Inspector Agency