BUREAU VERITAS

BV No. 237166

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: SEP 28.2023	Inspection Time: 10:30	Previous Sticker No. 21-9624 Issued By BV
Department / contractor: SUDHSR	Equipment Number: S40SG-125	Equipment Location: DAMMAM	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-9575
Manufacturer: GENIE	Model: SX125XC	Capacity: 500LBS / Type: MEWP	Equipment Serial Number: SX125D-168	Sticker Expiration Date: MARCH 27.2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI`s , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic Inspection and Function test for	
	Boom Supported Elevating work Platform	
	As per SAPCO GI 7.03, ANSI 92.5	
	"Pass"	

RECEIVER NAME: [illegible] SIGNATURE: [illegible] INSPECTOR NAME: [illegible]

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 8004411106

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency