BUREAU VERITAS

BV No. 0104275

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUAIMAH	Inspection Date: FEB 09, 2022	Inspection Time: -	Previous Sticker No. BV-21-1577 Issued By BV
Department / Contractor: SUDHIR	Equipment Number: S285G-134	Equipment Location: JUAIMAH NGL	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-3569
Manufacturer: GENIE	Model: S85	Capacity: 227 KG / Type: Man Lift	Equipment Serial Number: S85D-502	Sticker Expiration Date: AUG 08, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
#	periodic Inspection & Functional tests were carried out on	
	Boom supported Elevating work platform As per ANSI A92.5	
	and Aramco GI 7.030 and the Equipment was found	
	"satisfactory" at the time of Inspection	
#	Follow proper PM procedure regularly & Maintain good house keeping	
		20-0023

RECEIVER NAME: LIJU CHERIYAN SIGNATURE: INSPECTOR NAME: Ahmed Zouhem

BADGE#: 2379597343 TELEPHONE No.: 0580090118 TELEPHONE No.: 0550183638

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency