BUREAU VERITAS

BV No. 0105975

LIFTING EQUIPMENT INSPECTION REPORT	Area: JUBAIL	Inspection Date: JAN 11, 2023	Inspection Time: 9:00	Previous Sticker No. 21-3569 Issued By BV
Department / Contractor: SUDHIR	Equipment Number: S28SG-134	Equipment Location: L&T	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-7336
Manufacturer: GENIE	Model: S85	Capacity: 227KG / Type: MEWP	Equipment Serial Number: S85D-502	Sticker Expiration Date: JULY 10, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for	
	Boom supported elevating work platform	
	as per as SAUDI ARAMCO GI 7.030, ANSI 92.5	
	"PASS"	

RECEIVER NAME: THAISEER SIGNATURE: INSPECTOR NAME: M. OMAR

BADGE#: 8031 TELEPHONE No.: 055 222 8031 TELEPHONE No.: 18000

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency