BUREAU VERITAS

BV No. 0108430

LIFTING EQUIPMENT INSPECTION REPORT	Area: DAMMAM	Inspection Date: MARCH 12, 2023	Inspection Time: 11:00	Previous Sticker No. 4808 Issued By Zamil
Department / Contractor: SUDAIR	Equipment Number: S28SG-135	Equipment Location: DMM YARD	Equipment Result: ☑ Pass ☐ Fail	New Sticker No. BV-21-7733
Manufacturer: GENIE	Model: S85	Capacity: 227KG / Type: MEWP	Equipment Serial Number: S85D-503	Sticker Expiration Date: SEP 11, 2023

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection and Function test for	
	Boom supported Elevating work platform	
	As per SAUDI ARAMCO GI 7.030, WMSI 92.5	
	"Pass"	

RECEIVER NAME: THAISEER SIGNATURE: INSPECTOR NAME: MUMAR

BADGE#: TELEPHONE No.: TELEPHONE No.: 18...

When re-inspection requested, a complete copy of this report should be ready review by the inspector

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency