الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.
LEEA Full Member

CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)
02-Oct-2025	02-Oct-2025	DUB-L-0521	DUB/000285
Next Examination Due Date	**Date of last thorough Examination**	**Reference Standard**	**Order No**
01-Apr-2026	16-09-2024	BS EN 280-1:2022	W.O-DUB-LIF-02102025-003

Name and Address of Customer	Address of Examination
SUDHIR EQUIPMENT RENTAL COMPANY Duba, Kingdom of Saudi Arabia	Trojena, Kingdom of Saudi Arabia

Description and identification of the equipment	Equipment ID	Safe Working Load
MANLIFT (Telescopic Boom Lift) Manufacture: JLG Model: 860SJ / M.f.g year: 2017 ID No: S28SJ-138, Max Platform Height: 86 Ft, Horizontal Outreach: 75 Ft, Platform Capacity (Restricted):340 kg, Platform Capacity (Unrestricted): 227 kg, Max. wind speed: 5.2 m/s, G.V.W: 16329 Lbs.	B300002210	227 Kg

Is this first Examination after installation or assembly at new site or location?	NO	**Was the Examination carried out within an interval of 6 months?**	YES
Has the equipment been installed correctly?	YES	**Was the Examination carried out within an interval of 12 months?**	NO
In accordance with an Examination Scheme?	NO	**After the occurrence of exceptional circumstances?**	NO

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

N/A

Is the above an existing or imminent danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)	NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

N/A

Particulars of any tests carried out as part of the examination. And standard applied.

This ManLift has been Visual, Functional Examined in accordance with BS EN 280-1:2022.

Load Test(s): N/A

IS THIS EQUIPMENT SAFE TO OPERATE?	**YES**
Name and Signature of the person issue this certificate.	**Name and Signature of the person authenticating this certificate.**
Name: REMON RAj	**Name:** MOUSTAFA AHMED
Signature: Remon Raj. C	**Signature:**

Comments: At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual, maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.

QAVOC

The PDF document is electronically generated and digitally signed

الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.

LEEA
Full Member

Checklist

Certificate/Report Number: DUB-L-0521
Sticker Number(s): DUB/000285

INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection Certificate	☑	☐	☐
Last Third-party inspection sticker	☑	☐	☐
Operator Iqama/License/ Third Party	☑	☐	☐
Vehicle documents (Insurance & Estamara)	☑	☐	☐
Tire and air pressure	☑	☐	☐
Level Indicators	☑	☐	☐
Lights (include beacon light)	☑	☐	☐
Horn/ Reverse alarm	☑	☐	☐
Electrical switches and gauges	☑	☐	☐
Emergency lowering system	☑	☐	☐
Safety signs, labels and stickers	☑	☐	☐
Platform condition	☑	☐	☐
Greasing & lubrication of boom	☑	☐	☐
Overload Indicator	☑	☐	☐
Safe Access & Egress	☑	☐	☐
Fire extinguisher in good condition & valid	☑	☐	☐
Engine oil level, check system for damage, leak	☑	☐	☐
Hydraulic oil level, check system for leaks	☑	☐	☐
Transmission oil	☑	☐	☐

INSPECTION POINTS	Pass	Fail	N/A
Air filter	☑	☐	☐
Steering oil and steering system/Joystick	☑	☐	☐
Brakes and brake system (including parking brake)	☑	☐	☐
Fuel level and check for leaks in fuel system	☑	☐	☐
Coolant	☑	☐	☐
Radiator and hoses	☑	☐	☐
Fan belts and pulleys	☑	☐	☐
Hoses and fittings	☑	☐	☐
Battery	☑	☐	☐
Air Conditioner/Heater	☐	☐	☑
Boom lift, Boom extension & retraction (deflection)	☑	☐	☐
Lever controls & pedals	☑	☐	☐
Slewing mechanism	☑	☐	☐
Boom cylinder/Lifting cylinder	☑	☐	☐
Pneumatic system	☑	☐	☐
Identification & SWL Marking	☑	☐	☐
Hydraulic system	☑	☐	☐
Outrigger Jacks	☐	☐	☑
Operation	☑	☐	☐

Comments/Remarks:

N/A

Reference Documents:

BS EN 280-1:2022.

Inspected & witnessed by: REMON RAj

Signature: Remon Raj. C

Approved by: MOUSTAFA AHMED

Signature:

QA/QC
UNIVERSAL INSPECTION CO. LTD.

Doc No UIC FMT 091-A/Rev No. - 00
P.O Box no. 2072, Jubail-31951, KSA
Tel.: +966 13 344 8882/Fax.: +966 13 344 8881
Tel.: +966 13 367 0515
Website: www.ui.com.sa

ص.ب 2072 ، الجبيل 31951 - المملكة العربية السعودية
+هاتف: 966 13 344 8882 / فاكس: 966 13 344 8881+
+هاتف: 966 13 367 0515
الموقع الالكتروني www.ui.com.sa

The PDF document is electronically generated and digitally signed