BUREAU VERITAS

BV No. 0104463

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date FEB 02, 2022	Inspection Time —	Previous Sticker No. 21-1584 Issued By BV
Department / Contractor SUDHIR	Equipment Number SL3SJP-157	Equipment Location DMMYARD	Equipment Result ☑ Pass ☐ Fail	New Sticker No. BU-21-3224
Manufacturer JLG	Model 1350SJP	Capacity 500LBS / Type MEWP	Equipment Serial Number 0300254528	Sticker Expiration Date AUG 02, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and Function Test	
	For Boom Supported Elevating work Platform.	
	As per as S.Aramco GI 7.30. ANSI 92.5.	
	PASS	

RECEIVER NAME: N BAJDALIA SIGNATURE: [signature] INSPECTOR NAME: M. Jmars

BADGE#: TELEPHONE No.: TELEPHONE No.: 18009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency