National Inspection and Technical Testing FAHSS/TÜV Saudi Arabia

No.: 31200

LIFTING EQUIPMENT INSPECTION REPORT

Area	Org. Code	Inspection Date	Inspection Time	Previous Sticker No.	Issued by
DAMMAM	—	14JUL2020	13:00	06379	B.V

Department/Contractor	Equipment Number	Equipment Location	Inspection Result	New Sticker No.
EXPERTISE/SUDHIR	54056-168	LAY DOWN YARD	☑ Pass ☐ Fail	44035

Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GENIE	SX12SXC	454 KG	MANLIFT	SX1250-833	14JAN.2021

Above Equipment was inspected by FAHSS/TÜV in accordance with applicable Saudi Aramco GI's ASME and API standards. Defieciencies that require corrective action are listed below. Specific repairs to correct each defieciency should be noted in the corrective action taken column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	VISUAL AND FUNCTIONAL INSPECTION	
	FOUND SATISFACTORY.	

RECEIVER NAME : AKOD	SIGNATURE :	INSPECTORS NAME : QAISAR-09-0664
BADGE #:	TELEPHONE NO.:	TELEPHONE NO.: 0554606839

When re-inspetion is requested, a complete copy of this report should be ready reviewed by the inspector. Distribution : Original - Proponent; 1St Copy - FAHSS/TÜV, 2nd Copy - Inspector