ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 18-11-2024		Report Number : ESICO-LFT-R24-1786		
Name & Address of employer		Location	Sticker No	Standards
Sudhir Equipment Rental Company		Second Industrial Area-Dammam	3428	ANSI A92.5/CSAB354.4/AS 1418.10
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
B300027413	Articulated Boom Lift (ManLift) Model number: 450AJ Driving Propulsion: Diesel Working Height of 15,8 m and maximun of 7,5m horizontal reach. Consumption(average/h): 7,60kwh. Up & over height: 6.09m Transport dimension: (d x w x h) 6.58m x 2.36m x 2.27m Platform diamensions (d x w): 1,83 x 0,76m. Gradeability: 45,00% Own weight: 6.495kg. platform height:13.80meters	Mass: 2570kg	2024	JLG

Is this the first examination after installaton or assembly at a new site or location?	Yes	✓	No	-	Was the examination carried out within an interval of?	- 6 Months	
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	✓	No	-	In accordance with an examination scheme?	Yes ✓	No -
					After the occurence of exceptional circumstances?	Yes -	No ✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : No
Particulars of any repair, renewal or alteration required to remedy the defect identified above : No	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : Visual Inspection and function checks was performed at the time inspection, equipment was fit for purpose.	

For confirmation scan QR code
search with report number : ESICO-LFT-R24-1786

QA/QC DEPARTMENT

Safe to operate

Next Inspection : 17-05-2025

Inspected by : Michael Arthur