BUREAU VERITAS

BV No. 0104494

LIFTING EQUIPMENT INSPECTION REPORT	Area: GHAZAL	Inspection Date: FEB 20, 2022	Inspection Time: —	Previous Sticker No. 21-0581 Issued By: BV
Department / Contractor: SUDHIR	Equipment Number: S28S6-172	Equipment Location: JGC	Equipment Result: ☑ Pass ☐ Fail	New Sticker No.: BV-21-3256
Manufacturer: GENIE	Model: S85	Capacity: 227KG / Type: MEWP	Equipment Serial Number: S85D-801	Sticker Expiration Date: AUG 19, 2022

Above Equipment was inspected by Bureaeu Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
#	Periodic Inspection and function test for	
	Boom supported elevating work platform.	
	As per as SAROMCO GI 7.030, ANSI 92.5	
	"PASS"	

RECEIVER NAME: UBAYD ALA SIGNATURE: INSPECTOR NAME: M. AMARA

BADGE#: TELEPHONE No.: TELEPHONE No.: 18009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency